Temperature by Number of O-ring Failures 80 -Temperature(F) factor(O.ring.total) 60 -Number of O-ring Failures