Pressure by Number of O-ring Failures 200 -Pressure(psi) - 001 factor(O.ring.total) 50 **-**Number of O-ring Failures