Production Overview



Defect Rate Analysis by Plant & Shift

Top Defect Types & Root Cause Patterns

Supplier Performance & Material Cost Analysis



Quality Improvement Roadmap & Targets

- SwiftMotors should focus on reducing defects, lowering downtime, improving supplier quality, and training workers. Achieving these targets will help the company reach Six Sigma quality standards.

Edit

Analytics Filters

Jump to the end of the scene to 0:10.0

Top Defect Types & Root Cause Patterns

Prev scene Next scene Scene 1 of 6 0:03.0 0:10.0

Edit

Analytics Filters

Production Overview

- Pune, Chennai, and Ahmedabad together contribute to total vehicle production. This scene shows which plant has the highest output and which plant needs improvement.

Units Defective

518

Units Defective

Units Produced

11.9K

Units Produced

Defect Rate %

4.34

Defect Rate %

Prev scene Next scene Scene 2 of 6 0:03.5 0:05.0

Defect Rate Analysis by Plant & Shift

- Night shift has the highest defect rate in most plants. Certain supervisors and assembly lines consistently show higher defects and require closer monitoring.



Edit
Analytics
Filters

Top Defect Types & Root Cause Patterns

- The most common defects are mainly caused by rework issues, poor raw material quality, and assembly line mistakes. Defects that require rework increase scrap and production cost.



Prev scene
Next scene
Scene 4 of 6
0:03.7
0:05.0

Supplier Performance & Material Cost Analysis

- Some suppliers provide lower-cost materials but create more scrap. The best supplier is the one with lower cost and lower scrap units.



Edit
Analytics
Filters

Quality Improvement Roadmap & Targets

- SwiftMotors should focus on reducing defects, lowering downtime, improving supplier quality, and training workers. Achieving these targets will help the company reach Six Sigma quality standards.

Prev scene
Next scene
Scene 6 of 6
0:03.0
0:05.0

Edit

Analytics Filters

Production Overview



Defect Rate Analysis by Plant & Shift

Top Defect Types & Root Cause Patterns

Supplier Performance & Material Cost Analysis



Quality Improvement Roadmap & Targets

- SwiftMotors should focus on reducing defects, lowering downtime, improving supplier quality, and training workers. Achieving these targets will help the company reach Six Sigma quality standards.

Prev scene Next scene 6 scenes 0:00.0 0:00.0