32X TECHNICAL BULLETIN #10

To: Sega and Third Party Developers

From: Developer Technical Support

Date: September 23, 1994

Re: free run timer initialization

Initialization of the free run timer must be done whether or not interrupt is used in coping with SH2 interrupt.