## 32X TECHNICAL BULLETIN #9

To: Sega and Third Party Developers

From: Developer Technical Support

Date: September 23, 1994

Re: 68K interrupts & RV bit = 1

All 68000 interrupts must be prohibited during the period that the RV bit = 1.