### AIR CONTAMINANTS DATA

Emission	Source	Air Contaminant	<b>Emission</b>	Rates *	· •
Point No. (1)	Name (2)	Name (3)	lb/hr	TPY	_
	EMISSION	SOURCES - MAXI	MUM ALL	OWABL	E EMISSION RATES

Permit No. 5667

This table lists the maximum allowable emission rates and all sources of air contaminants on the applicant's property covered by this permit. The emission rates shown are those derived from information submitted as part of the application for permit and are the maximum rates allowed for these facilities. Any proposed increase in emission rates may require an application for a modification of the facilities covered by this permit.

Emission Point No. (1)	Source Name (2)	Name (3)	Air Contaminant lb/hr TPY	Emission Rates *	
E-23A	Furnace 3		PM10 VOC NOx SO2 CO	21.11 0.12 19.41 9.03 0.52	92.46 0.53 85.02 39.54 2.28
E-24A	Furnace 4		PM10 VOC NOx SO2 CO	21.11 0.12 19.41 9.03 0.52	92.46 0.53 85.02 39.54 2.28
E-27	Batch Hold Bi Baghouse	n 3	PM10	0.25	1.07
E-28	Batch Hold Bi Baghouse	n 4	PM10	0.25	1.07
E-34, A-D	Hot Air Dryer		PM10 VOC NOx SO2	0.03 1.58 0.54 <0.01	0.10 5.90 2.02 0.03

Emission	Source	Air Contaminant	Emission I	Rates *		
Point No. (1)	Name (2)	Name (3)	lb/hr	TPY		
				СО	0.11	0.41
E-35, A-D	Hot	Air Dryer 35		PM10	0.03	0.10
				VOC	1.58	5.90
				NOx	0.54	2.02
				SO2	< 0.01	0.03
				CO	0.11	0.41
E-36, A-D	Hot	Air Dryer 36		PM10	0.03	0.10
				VOC	1.58	5.90
				NOx	0.54	2.02
				SO2	<0.01	0.03
				CO	0.11	0.41

Emission Source Point No. (1) Name E-37	Air Contaminant Emission (2) Name (3) lb/hr Chopped Strand Unit 1 Dryer	Rates * TPY PM10 VOC NOx SO2 CO	0.03 0.34 0.12 <0.01 0.02	0.11 1.49 0.51 0.09 0.10
E-39	Chopped Strand Unit 2 Dryer	PM10 VOC NOx SO2 CO	0.49 0.57 0.19 <0.01 0.04	1.07 1.24 0.42 <0.01 0.09
E-40	Chopped Strand Unit 3 Dryer	PM10 VOC NOx SO2 CO	0.25 0.34 0.12 <0.01 0.02	0.54 0.74 0.25 <0.01 0.05
E-42, A and B	Dielectric Oven 42	VOC	0.14	0.61
E-83	Forming Line Scrubber	PM10 VOC	0.82 0.03	0.36 0.13
E-84	Forming Line Scrubber	PM10 VOC	0.82 0.03	0.36 0.13
E-93	Furnace 3 Forehearth	PM10 VOC NOx SO2 CO	0.03 0.02 0.81 <0.01 0.20	0.13 0.07 3.56 0.04 0.89
E-94	Furnace 4 Forehearth	PM10 VOC NOx SO2 CO	0.03 0.02 0.81 <0.01 0.20	0.13 0.07 3.56 0.04 0.89

### AIR CONTAMINANTS DATA

Emission Source	Air Contaminant Emission I	Rates *		
Point No. (1) Name	e (2) Name (3) lb/hr	TPY		
E-99	RTP Dryer 10	PM10	0.03	0.07
		VOC	0.57	1.24
		NOx	0.19	0.42
		SO2	< 0.01	< 0.01
		CO	0.04	0.09
E-100	RTP Dryer 11	PM10	0.04	0.17
	,	VOC	0.57	1.24
		NOx	0.19	0.42
		SO2	< 0.02	< 0.01
		CO	0.04	0.09
E-108	Shrink Wrap Dryer	PM10	0.04	0.17
	• •	VOC	< 0.01	0.02
		NOx	0.08	0.34
		SO2	< 0.01	< 0.01
		CO	0.02	0.07
E-110	Direct Chop Baghouse	PM10	0.32	1.41
E-111	RTP Choppers	PM10	0.44	1.93

SO2 - sulfur dioxide

CO - carbon monoxide

<sup>(1)</sup> Emission point identification - either specific equipment designation or emission point number from plot plan.

<sup>(2)</sup> Specific point source name. For fugitive sources use area name or fugitive source name.

<sup>(3)</sup> PM10 - particulate matter less than 10 microns

VOC - volatile organic compounds as defined in General Rule 101.1

NOx - total oxides of nitrogen

<sup>\*</sup> Emission rates are based on and the facilities are limited by the following maximum operating schedule:

Permit No. 5667 Page 5

# EMISSION SOURCES - MAXIMUM ALLOWABLE EMISSION RATES

Emission	Source	Air Contaminant	<b>Emission</b>	Rates *
Point No. (1)	Name (2)	Name (3)	lb/hr	TPY
		Hrs	s/year 8,7	60