#### Permit No. 6048

This table lists the maximum allowable emission rates and all sources of air contaminants on the applicant's property covered by this permit. The emission rates shown are those derived from information submitted as part of the application for permit and are the maximum rates allowed for these facilities. Any proposed increase in emission rates may require an application for a modification of the facilities covered by this permit.

## AIR CONTAMINANTS DATA

Emission Point No. (1)	Source Name (2) Name (3)	Air Contaminant lb/hr TPY	<u>Emission</u>	Rates *
1	Clay Crushing and Handling	РМ	0.033	0.14
2	Clay Transfer	PM	0.001	0.005
3	Iron Ore Handling	PM	0.0001	0.0005
4	Limestone and Clay Bins with Transfer Points	РМ	0.006	0.03
5	Coal, Coke, Gypsum, and Clinker Transfer	РМ	0.003	0.014
6	Coal/Coke Handling	PM	0.87	3.81
7	Aeropol Conveyor	PM	0.006	0.03
8	Blending Silo	PM	0.006	0.03
9	Kiln Feed System	PM	0.013	0.06
10	Kiln Stack	PM NOx SO2 CO VOC	25.5 292.4 106.0 256.8 10.5	112.0 1281.0 100.0 1125.0 46.0
11	Dust Handling	PM	0.0002	0.0006
12	Clinker Cooler	PM	14.9	65.0

## AIR CONTAMINANTS DATA

Emission Source	Air Contaminant	Emission Rates *		
Point No. (1) Nam	e (2) Name (3)	lb/hr TPY_		
13	Clinder Transfer to Deep Bucket	РМ	0.004	0.02
14	Clinker Hopper and Transfer Points	PM	0.0002	0.001
15	Clinker Silo and Transfer	РМ	0.004	0.02
16	Clinker Transfer North	РМ	0.002	0.01
17	Clinker Transfer South	РМ	0.002	0.01
18	Gypsum Transfer	PM	0.0002	0.001
19	North Finish Mill	PM	2.53	11.1
20	Finish Mill and Transfer Points North	РМ	0.006	0.03
21	South Finish Mill	PM	1.24	5.4
22	Finish Mill with Transfer Points South	PM	0.003	0.013
23	Cement Silo Transfer	РМ	0.004	0.02
24	Cement Silo Distribution System North	п РМ	0.002	0.009
25	Cement Silo Transfer	РМ	0.004	0.02
26	Cement Silo Distribution System South	n PM	0.002	0.01

### AIR CONTAMINANTS DATA

Emission Source Point No. (1) Name	Air Contaminant <u>Emission</u> e (2) Name (3) lb/hr	Rates * TPY		
27	Cement Loading Station Transfer	PM	0.004	0.02
28	Cement Loading Station Transfer	PM	0.004	0.02
29	Cement Loading Station Transfer	PM	0.004	0.02
30	Clinker Transfer	PM	0.0001	0.0004
31	Cement Silo Transfer	PM	0.005	0.02
32	Cement Silo Transfer	PM	0.0001	0.0005
33	Finish Mill Transfer	PM	0.0001	0.0005

For Fugitive Emission estimates see Table 1(a) date stamped July 2, 1993 in Permit File No. 6048.

- (1) Emission point identification either specific equipment designation or emission point number from plot plan.
- (2) Specific point source name. For fugitive sources use area name or fugitive source name.
- (3) PM particulate matter
  - VOC volatile organic compounds as defined in General Rule 101.1
  - NOx total oxides of nitrogen
  - SO2 sulfur dioxide
  - CO carbon monoxide
- (4) Fugitive emissions are an estimate only and should not be considered as a maximum allowable emission rate.
- \* Emission rates are based on and the facilities are limited by the following maximum operating schedule:

Hrs/day 24 Days/week 7 Weeks/year 52 or Hrs/year 8,760

## AIR CONTAMINANTS DATA

Emission	Source	Air Contaminant	<b>Emission</b>	Rates *
Point No. (1)	Name (2)	Name (3)	lb/hr	TPY

Dated	
_ 00	