BiztelAI - Assignment Sample Questions

Use these questions to test your copilot. Then write 5 questions of your own, including at least one that the documents cannot answer, and show how your app responds to each.

1. What is the recommended coolant concentration for the TX-200 CNC turning centre?
2. The machine is showing alarm AL-104. What does it mean and what should the operator do?
3. Who is allowed to remove a lockout lock from a machine?
4. What is the outer diameter tolerance for the BH-220 bearing housing?
5. How often should spindle runout be checked, and who does it?