

FAULT CODE 235 - Coolant Level - Data Valid But Below Normal Operating Range - Most Severe Level

Troubleshooting Summary

STEPS		SPECIFICATIONS
STEP 1.	Check the fault codes.	
	STEP 1A. Check for Fault Code 235.	Active or inactive counts of Fault Code 235?

STEP 1. Check the fault codes.

STEP 1A. Check for Fault Code 235.

Conditions :

- Turn keyswitch ON.
- Connect INSITE™ electronic service tool.

Action	Specification/Repair	Next Step
--------	----------------------	-----------

Check for fault codes. • Use INSITE™ electronic service tool to read the fault codes.	Active or inactive counts of Fault Code 235? YES Repair : Reference the Coolant Loss troubleshooting symptom tree in the Service Manual QSK19 CM850 and QSK19 CM2150 Modular Common Rail System Series Engines, Bulletin 4021592. If Fault Code 235 is active and the coolant level is not low, a malfunctioning coolant level sensor is a likely cause. Refer to the OEM service manual before replacing the coolant level sensor.	Go to the appropriate troubleshooting steps.
	Active or inactive counts of Fault Code 235? NO	Repair complete.