

Trainings ▾

Inspect

Every 6000 hours or 2 years inspect the fan idler pulley assembly. Rebuild or replace the idler pulley as necessary.

Refer to a Cummins Authorized Repair Location for rebuild or replacement instructions.

