


Trainings ▾

Remove

with Mechanically Actuated Injector

It is a good service practice to mark the push rods so they can be installed in their original position.

Remove the push rods and crossheads.



with Electronically Actuated Injector

It is recommended a service practice to mark the push rods so they can be installed in their original position.

Remove the push rods.

