

Trainings ▾

Inspect

Every 6000 hours or 2 years, inspect the fan drive idler pulley assembly. Rebuild or replace the idler pulley as necessary. Contact a Cummins® Authorized Repair Location.

