

Trainings ▾


Tool Number

ST-1138

Belt Tensioner Gauge

Used to measure alternator belt tension.

©Cummins Inc



fa8togg



Tool Number

3377161

Digital Multimeter Kit

Used to measure up to 750 AC current (amps) and 1000 DC voltage (VDC), or resistance (ohms). Kit is complete with test leads and alligator clips.

©Gammline Inc



3377161


Tool Number

3164488

Digital Multimeter

Used to measure up to 750 AC current (amps) and 1000 DC voltage (VDC), or resistance (ohms).

©Gummine Inc



3376898



Tool Number

3164489

Digital Multimeter

Used to measure frequency, capacitance, temperature (with a built-in temperature module), RPM, dwell, duty cycle, and pulse width.

©Gammline Inc



3377161


Tool Number

3164490

Clamp On Current Probe

Used to measure AC and DC currents. This unit must be used with digital multimeter, Part Number 3164488 or 3377161.

©Gammill Inc



3823574