


Trainings ▾

Inspect

⚠ CAUTION ⚠

The silicon fluid in the vibration damper will become solid after extended service and will make the damper inoperative. An inoperative vibration damper can cause major engine or drivetrain malfunction.



Check the vibration damper for evidence of fluid loss, dents, and wobble. Inspect the vibration damper thickness for any deformation or raising of the damper cover plate.

If any of these conditions are identified, contact your local Cummins Authorized Repair Location to replace the vibration damper.

Viscous dampers have a limited life. Refer to Section V for maximum damper life specifications.

For vibration damper location, refer to Engine Diagrams in Section E