


Trainings ▾

Inspect

Inspect the water pump for coolant or oil leakage at the water pump weep hole.

Note : A minor chemical buildup or streaking at the water pump weep hole is normal. Do not repair or replace the water pump unless an actual leak is confirmed. Contact a Cummins® Authorized Repair Location.



08a00043