


Fault Code: 1519

At Least One Module Has A Least Severe Fault - Condition Exists

 Printable Version

Overview

Codes	Reason	Effect
Fault Code: 1519 PID(P): S254 SPN: 1484 FMI: 11/31 Lamp: Maintenance SRT:	A least severe fault code has been detected by at least one module	Possible reduced engine performance.



Engine Control Module (ECM)

Circuit Description

The engine control module (ECM) is a computer that is responsible for engine control, diagnostics, and user features. A least severe fault code has been detected from a ECM on the J1939 datalink network.

Component Location

The Engine Control Modules (ECM) are located on a plate that is above the flywheel housing.

Conditions For Running The Diagnostics

This diagnostic runs continuously when the generator set controller is active.

Conditions For Setting The Fault Codes

The Engine Control Module (ECM) has detected one or more least severe faults.

Action Taken When The Fault Code Is Active

- The generator set controller displays a warning fault immediately when the diagnostics runs and fails.

Conditions For Clearing The Fault Code

- This fault code will go inactive once all amber lamp fault codes in secondary ECMs are inactive.
- The generator set controller will turn off the warning indicator immediately after the user presses reset.
- The “Reset All Faults” command in the recommended Cummins® electronic service tool or equivalent can be used to clear active faults.

Shoptalk

Each ECM has an individual source address that displays when the recommended Cummins® electronic service tool or equivalent is connected. When troubleshooting a fault code, use the source address displayed in the recommended Cummins® electronic service tool or equivalent to determine which ECM and circuit is affected.

Possible causes of this fault code include:

- A least severe fault code detected on another ECM.

Refer to Troubleshooting Fault Code 1519 . (</qs3/pubsys2/xml/en/procedures/60/60-t05-1519.html>)