


Fault Code: 343

Engine Control Module Warning Internal Hardware Failure - Bad Intelligent Device or Component

 Printable Version

Overview

Codes	Reason	Effect
Fault Code: 343 PID(P): S254 SPN: 629 FMI: 12/12 Lamp: Amber SRT:	An internal ECM communication failure has been detected.	Possible reduced engine performance.



Engine Control Module (ECM)

Circuit Description

The engine control module (ECM) receives constant voltage from the batteries through the unswitched battery wires that are connected directly to the positive (+) battery post. The ECM receives switched battery input through the keyswitch wire when the keyswitch is turned ON.

Component Location

The Engine Control Modules (ECM) are located on a plate that is above the flywheel housing.

Conditions For Running The Diagnostics

This diagnostic runs continuously when the generator set controller is active.

Conditions For Setting The Fault Codes

The Engine Control Module (ECM) detected a read or write error internal to the ECM.

Action Taken When The Fault Code Is Active

- The generator set controller displays a warning fault immediately when the diagnostics runs and fails.

Conditions For Clearing The Fault Code

- To validate the repair, start the engine and let it run for 1 minute at no load.
- The generator set controller will turn off the warning indicator immediately after the user presses reset.
- The “Reset All Faults” command in the recommended Cummins® electronic service tool or equivalent can be used to clear active faults.

Shoptalk

Possible causes of this fault code include:

- Internal ECM failure.

Refer to Troubleshooting Fault Code 343 . (</qs3/pubsys2/xml/en/procedures/60/60-t05-343.html>)