


Fault Code: 223

Burn Valve Solenoid Fault

 Printable Version

Overview

Codes	Reason	Effect
Fault Code: 223 PID(P): S085 SPN: 1265 FMI: 4/4 Lamp: Yellow SRT:	Incorrect voltage detected at the Centinel™ actuator circuit by the ECM.	None on performance. Centinel™ deactivated.



Burn Valve Solenoid

Circuit Description

The burn valve solenoid controls the flow of oil into the fuel drainline during the burn cycle.

Component Location

The burn valve solenoid is on top of the oil control valve. The oil control valve is on the left side of the engine below the fuel delivery housing.

Refer to Troubleshooting Fault Code t05-223 (/qs3/pubsys2/xml/en/procedures/82/82-t05-223.html)

Last Modified: 02-Sep-2010
