


Fault Code: 293 (INDUSTRIAL)

OEM Temperature Sensor Circuit

 Printable Version

Overview

Codes	Reason	Effect
Fault Code: 293 PID(P): S154 SPN: 1083 FMI: 3/3 Lamp: Yellow SRT:	High voltage detected at the OEM temperature sensor signal pin of the 31-pin OEM connector.	No engine protection for OEM temperature.



OEM Temperature Sensor Circuit

Circuit Description

The OEM sensor signal is used by the electronic control module (ECM) to monitor the OEM temperature. The OEM temperature is used by the ECM for the engine protection system. A sensor that has failed high can be caused by an open circuit in the signal or return wire, voltage shorts in the signal or return wire, or a faulty sensor.

Component Location

The location varies with the OEM. Refer to the OEM troubleshooting and repair manual.

Shoptalk

The resistance of all temperature sensors varies with the temperature.

Refer to Troubleshooting Fault Code t05-293 (</qs3/pubsys2/xml/en/procedures/82/82-t05-293.html>)

Last Modified: 02-Sep-2010
