


Fault Code: 388

Engine Brake Supply Circuit

 Printable Version

Overview

Codes	Reason	Effect
Fault Code: 388 PID(P): S079 SPN: 1072 FMI: 11 Lamp: Yellow SRT:	Less than 6 VDC detected at the engine brake circuit 1 when on indicates an excessive current draw from the electronic control module (ECM) or faulty ECM output circuit.	Engine brake 1 can not be activated.



Engine Brake Supply Circuit

Circuit Description

The ECM enables the engine brake by sending a signal directly to the engine brakes. The ECM will **only** enable the engine brakes under certain conditions.

Component Location

Refer to an OEM diagram for the location of the engine brake.

Shoptalk

A possible cause for this fault code is an ECM engine brake driver 1 short to ground.

Refer to Troubleshooting Fault Code t05-388 (</qs3/pubsys2/xml/en/procedures/82/82-t05-388.html>)

Last Modified: 02-Sep-2010
