


Fault Code: 536

Autoshift Low Gear Actuator (Lockout Solenoid)

 Printable Version

Overview

Codes	Reason	Effect
Fault Code: 536 PID(P): S044 SPN: 718 FMI: 11/11 Lamp: Yellow SRT:	Either low voltage detected on autoshift low gear actuator circuit when + 12 VDC are commanded or voltage detected when no voltage is commanded.	Top 2 lockout solenoid will not function properly. Transmission will not shift properly.



Top 2 Lockout Solenoid Circuit

Circuit Description

The autoshift low gear actuator is an ECM-driven solenoid that controls a Top 2 transmission.

Component Location

The autoshift low gear actuator is located on the topside of a transmission toward the back. Refer to an OEM diagram for a specific location.

Refer to Troubleshooting Fault Code t05-536 (/qs3/pubsys2/xml/en/procedures/82/82-t05-536.html)

Last Modified: 02-Sep-2010
