

Fault Code: 343


Electronic Control Module (ECM) Internal Communication Error

 Printable Version

Overview

Codes	Reason	Effect
Fault Code: 343 PID(P): S254 SPN: 629 FMI: 12 Lamp: Yellow SRT:	Microprocessor communication error internal to the ECM.	Variable; performance will or will not be affected.

©Cummins Inc



19900397

Electronic Control Module (ECM)

Circuit Description

The ECM is a computer that is responsible for engine control, diagnostics, and user features.

Component Location

An ECM is located on both sides of the engine in front of the fuel pump.

Shoptalk

This is a fault with the internal circuitry of the ECM. There are no repairs possible for the module in the field.

Refer to Troubleshooting Fault Code t05-343 (</qs3/pubsys2/xml/en/procedures/87/87-t05-343.html>)

Last Modified: 29-Jul-2010
