

Manual Change History (2883582) Marine Auxiliary QSM11-DM CM570 Owners Manual

Date	07-Feb-2012
Section	Back
Procedure Number	2883582-history (/qs3/pubsys2/xml/en/manual/2883582/2883582-history.html)
Procedure Title	Manual Change History
Update Reason	New manual for Marine Auxiliary QSM11-DM CM570 engine released for use.
Date	03-Apr-2014
Section	Section V - Maintenance Specifications
Procedure Number	101-018-003-owner-ind (/qs3/pubsys2/xml/en/procedures/101/101-018-003-owner-ind.html)
Procedure Title	Lubricating Oil Recommendations and Specifications
Update Reason	10W-30 oil is only for use in 2010 ISX 12/15 liter product and is not allowed or recommended for 2007 and earlier engines. Not allowed in any dual overhead camshaft engines.
Date	14-May-2018
Section	Section V - Specifications
Procedure Number	35-018-024-owner-marau (/qs3/pubsys2/xml/en/procedures/35/35-018-024-owner-marau.html)
Procedure Title	Filter Specifications
Update Reason	Updated Fleetguard® lubricating oil filter part number.