

Manual Change History (5411481) C Command Connect and Connect Premier Marine Panel System PS102, PS103 and PS108

Date	04-Apr-2017
Section	Back
Procedure Number	5411481-history (/qs3/pubsys2/xml/en/manual/5411481/5411481-history.html)
Procedure Title	Manual Change History
Update Reason	New manual for C Command Connect and Connect Premier Marine Panel System PS102 released for use.

Date	02-Jun-2017
Section	Section 1 - Operating Instructions
Procedure Number	513-101-013 (/qs3/pubsys2/xml/en/procedures/513/513-101-013.html)
Procedure Title	General Operating Instructions
Update Reason	Added the following Caution: If a non-Cummins® supplied engine instrumentation and/or alarm system is utilized, it is the owner's responsibility to verify the engine alarm communication (visual and audible) to the operator is enabled and functional while operating the engine. • This includes aftermarket additions or modifications to the engine instrumentation and/or alarm system. • Be aware that software updates to non-Cummins® supplied engine instrumentation may inadvertently disable the engine instrumentation and/or alarm functionality. • Cummins Inc. is not responsible for failures or damage resulting from use of engine instrumentation and alarm systems that are not supplied by a Cummins® factory.

Date	09-Aug-2019
Section	Section E - Product and System Identification
Procedure Number	513-208-002 (/qs3/pubsys2/xml/en/procedures/513/513-208-002.html)
Procedure Title	Component Diagrams
Update Reason	Added conditional information to include the PS103 engine.

Date	22-Aug-2019
Section	Section E - Product and System Identification
Procedure Number	513-344-003 (/qs3/pubsys2/xml/en/procedures/513/513-344-003.html)
Procedure Title	Cummins® Product Technology
Update Reason	Added conditional information to include the PS103 engine.

Date	23-Aug-2019
Section	Section L - Service Literature
Procedure Number	513-205-001 (/qs3/pubsys2/xml/en/procedures/513/513-205-001.html)
Procedure Title	Additional Service Literature
Update Reason	Added conditional information to include the PS103 engine.

Date	10-Apr-2025
Section	Section L - Service Literature
Procedure Number	513-205-001 (/qs3/pubsys2/xml/en/procedures/513/513-205-001.html)
Procedure Title	Additional Service Literature
Update Reason	Additional information to include the PS108 engine.

Date	17-Apr-2025
Section	Section 1 - Operating Instructions
Procedure Number	513-101-137 (/qs3/pubsys2/xml/en/procedures/513/513-101-137.html)
Procedure Title	System Indicator Lamps
Update Reason	Added references to ED-5/ED-7 and PS108 to procedure.
Date	21-Apr-2025
Section	Section E - Product and System Identification
Procedure Number	513-344-003 (/qs3/pubsys2/xml/en/procedures/513/513-344-003.html)
Procedure Title	Cummins® Product Technology
Update Reason	Added PS108 reference to procedure.

Last Modified: 25-Apr-2025
