

Manual Change History (5612991) QSM11 CM570 Fault Code

Troubleshooting Manual Change History

Date	04-Jul-2026
Fault Code / Symptom	High Blowby
Solution Number	S00011119
Solution Title	Plugged crankcase breather component (internal)
Update Reason	Solution Added

Date	26-Jan-2026
Fault Code / Symptom	Engine Oil Rifle Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00012663
Solution Title	Lubricating oil pressure sensor stuck in-range
Update Reason	Solution Added

Date	26-Jan-2026
Fault Code / Symptom	Engine Oil Rifle Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000342
Solution Title	Lubricating oil pressure sensor stuck in-range
Update Reason	Solution Removed

Date	18-Jan-2026
Fault Code / Symptom	Intake Manifold 1 Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00000485
Solution Title	Radiator is externally obstructed
Update Reason	Solution Removed

Date	26-Oct-2025
Fault Code / Symptom	Runs Rough or Misfires
Solution Number	S00000553
Solution Title	Verify performance complaint
Update Reason	Solution Removed

Date	18-Aug-2025
Fault Code / Symptom	Coolant Temperature High
Solution Number	S00012542
Solution Title	Thermostat is malfunctioning
Update Reason	Solution Added
Date	18-Aug-2025
Fault Code / Symptom	Coolant Temperature High
Solution Number	S00001299
Solution Title	Thermostat is malfunctioning
Update Reason	Solution Removed
Date	18-Aug-2025
Fault Code / Symptom	Coolant Temperature High
Solution Number	S00001359
Solution Title	Out-of-chassis opening temperature test
Update Reason	Solution Removed
Date	18-Aug-2025
Fault Code / Symptom	Coolant Temperature Low
Solution Number	S00012542
Solution Title	Thermostat is malfunctioning
Update Reason	Solution Added
Date	18-Aug-2025
Fault Code / Symptom	Coolant Temperature Low
Solution Number	S00001299
Solution Title	Thermostat is malfunctioning
Update Reason	Solution Removed
Date	18-Aug-2025
Fault Code / Symptom	Coolant Temperature Low
Solution Number	S00001359
Solution Title	Out-of-chassis opening temperature test
Update Reason	Solution Removed

Date	18-Aug-2025
Fault Code / Symptom	Engine Coolant Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00012515
Solution Title	Thermostat is malfunctioning
Update Reason	Solution Added

Date	18-Aug-2025
Fault Code / Symptom	Engine Coolant Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00000785
Solution Title	Thermostat is malfunctioning
Update Reason	Solution Removed

Date	18-Aug-2025
Fault Code / Symptom	Engine Coolant Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00001359
Solution Title	Out-of-chassis opening temperature test
Update Reason	Solution Removed

Date	18-Aug-2025
Fault Code / Symptom	Intake Manifold 1 Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00012515
Solution Title	Thermostat is malfunctioning
Update Reason	Solution Added

Date	18-Aug-2025
Fault Code / Symptom	Intake Manifold 1 Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00000785
Solution Title	Thermostat is malfunctioning
Update Reason	Solution Removed

Date	18-Aug-2025
Fault Code / Symptom	Intake Manifold 1 Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00001359
Solution Title	Out-of-chassis opening temperature test
Update Reason	Solution Removed
Date	21-Jul-2025
Fault Code / Symptom	External Lubricating Oil Leak
Solution Number	S00012455
Solution Title	Fluorescent Dye Tracer Test (lubricating oil)
Update Reason	Solution Added
Date	21-Jul-2025
Fault Code / Symptom	Lubricating Oil Consumption
Solution Number	S00012455
Solution Title	Fluorescent Dye Tracer Test (lubricating oil)
Update Reason	Solution Added
Date	21-Jul-2025
Fault Code / Symptom	Lubricating Oil Level Low
Solution Number	S00012455
Solution Title	Fluorescent Dye Tracer Test (lubricating oil)
Update Reason	Solution Added
Date	01-Jun-2025
Fault Code / Symptom	Auxiliary Temperature Sensor Input 1 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00003211
Solution Title	OEM temperature sensor open circuit check
Update Reason	Solution Reordered

Date	01-Jun-2025
Fault Code / Symptom	Auxiliary Temperature Sensor Input 1 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00003211
Solution Title	OEM temperature sensor open circuit check
Update Reason	Solution Modified

Date	01-Jun-2025
Fault Code / Symptom	Auxiliary Temperature Sensor Input 1 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00003214
Solution Title	OEM temperature sensor circuit pin to pin short
Update Reason	Solution Reordered

Date	01-Jun-2025
Fault Code / Symptom	Auxiliary Temperature Sensor Input 1 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00003214
Solution Title	OEM temperature sensor circuit pin to pin short
Update Reason	Solution Modified

Date	01-Jun-2025
Fault Code / Symptom	Auxiliary Temperature Sensor Input 1 Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00003214
Solution Title	OEM temperature sensor circuit pin to pin short
Update Reason	Solution Reordered

Date	01-Jun-2025
Fault Code / Symptom	Auxiliary Temperature Sensor Input 1 Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00003214
Solution Title	OEM temperature sensor circuit pin to pin short
Update Reason	Solution Modified
Date	26-May-2025
Fault Code / Symptom	Intake Manifold 1 Pressure Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000411
Solution Title	Intake manifold pressure sensor circuit response
Update Reason	Solution Reordered
Date	26-May-2025
Fault Code / Symptom	Intake Manifold 1 Pressure Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000411
Solution Title	Intake manifold pressure sensor circuit response
Update Reason	Solution Modified
Date	26-May-2025
Fault Code / Symptom	Intake Manifold 1 Pressure Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000758
Solution Title	Intake manifold pressure sensor voltage check at the engine control module
Update Reason	Solution Reordered

Date	26-May-2025
Fault Code / Symptom	Intake Manifold 1 Pressure Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000758
Solution Title	Intake manifold pressure sensor voltage check at the engine control module
Update Reason	Solution Modified
Date	26-May-2025
Fault Code / Symptom	Intake Manifold Pressure Sensor Circuit - Data erratic, intermittent or incorrect
Solution Number	S00000758
Solution Title	Intake manifold pressure sensor voltage check at the engine control module
Update Reason	Solution Reordered
Date	26-May-2025
Fault Code / Symptom	Intake Manifold Pressure Sensor Circuit - Data erratic, intermittent or incorrect
Solution Number	S00000758
Solution Title	Intake manifold pressure sensor voltage check at the engine control module
Update Reason	Solution Modified
Date	18-May-2025
Fault Code / Symptom	Intake Manifold 1 Pressure Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000457
Solution Title	Intake manifold pressure sensor voltage check
Update Reason	Solution Removed
Date	18-May-2025
Fault Code / Symptom	Intake Manifold 1 Pressure Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000758
Solution Title	Intake manifold pressure sensor voltage check at the ECM
Update Reason	Solution Removed

Date	18-May-2025
Fault Code / Symptom	Intake Manifold 1 Pressure Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000352
Solution Title	Intake manifold pressure sensor circuit response
Update Reason	Solution Reordered
Date	18-May-2025
Fault Code / Symptom	Intake Manifold 1 Pressure Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000352
Solution Title	Intake manifold pressure sensor circuit response
Update Reason	Solution Modified
Date	18-May-2025
Fault Code / Symptom	Intake Manifold 1 Pressure Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000457
Solution Title	Intake manifold pressure sensor voltage check
Update Reason	Solution Reordered
Date	18-May-2025
Fault Code / Symptom	Intake Manifold 1 Pressure Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000457
Solution Title	Intake manifold pressure sensor voltage check
Update Reason	Solution Modified
Date	18-May-2025
Fault Code / Symptom	Intake Manifold Pressure Sensor Circuit - Data erratic, intermittent or incorrect
Solution Number	S00000457
Solution Title	Intake manifold pressure sensor voltage check
Update Reason	Solution Reordered

Date	18-May-2025
Fault Code / Symptom	Intake Manifold Pressure Sensor Circuit - Data erratic, intermittent or incorrect
Solution Number	S00000457
Solution Title	Intake manifold pressure sensor voltage check
Update Reason	Solution Modified
Date	26-Aug-2024
Fault Code / Symptom	Blue Smoke
Solution Number	S00001375
Solution Title	Plugged external crankcase breather tube
Update Reason	Solution Removed
Date	26-Aug-2024
Fault Code / Symptom	Blue Smoke
Solution Number	S00001203
Solution Title	Turbocharger leaking air into crankcase
Update Reason	Solution Removed
Date	26-Aug-2024
Fault Code / Symptom	Engine Decelerates Slowly
Solution Number	S00003094
Solution Title	Turbocharger leaking air into crankcase
Update Reason	Solution Removed
Date	26-Aug-2024
Fault Code / Symptom	High Blowby
Solution Number	S00001375
Solution Title	Plugged external crankcase breather tube
Update Reason	Solution Removed
Date	26-Aug-2024
Fault Code / Symptom	High Blowby
Solution Number	S00001203
Solution Title	Turbocharger leaking air into crankcase
Update Reason	Solution Removed

Date	19-Aug-2024
Fault Code / Symptom	Crank No Start
Solution Number	S00012091
Solution Title	Fuel level check
Update Reason	Solution Added
Date	22-Jul-2024
Fault Code / Symptom	Engine Speed Surges
Solution Number	
Solution Title	
Update Reason	Solution Set Removed
Date	22-Jul-2024
Fault Code / Symptom	Intake Manifold Pressure Sensor Circuit - Data erratic, intermittent or incorrect
Solution Number	S00000025
Solution Title	Restricted intake air filter
Update Reason	Solution Reordered
Date	22-Jul-2024
Fault Code / Symptom	Intake Manifold Pressure Sensor Circuit - Data erratic, intermittent or incorrect
Solution Number	S00000025
Solution Title	Restricted intake air filter
Update Reason	Solution Modified
Date	12-May-2024
Fault Code / Symptom	Coolant Level - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00007920
Solution Title	Coolant level sensor open circuit check
Update Reason	Solution Removed
Date	12-May-2024
Fault Code / Symptom	Coolant Level - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00007921
Solution Title	Coolant level sensor circuit pin to ground short
Update Reason	Solution Removed

Date	12-May-2024
Fault Code / Symptom	Coolant Level - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00007922
Solution Title	Coolant level sensor circuit pin to pin short
Update Reason	Solution Removed
Date	07-Apr-2024
Fault Code / Symptom	Fuel Consumption Excessive
Solution Number	S00003075
Solution Title	Incorrect adjustable parameter setting
Update Reason	Solution Reordered
Date	07-Apr-2024
Fault Code / Symptom	Fuel Consumption Excessive
Solution Number	S00003075
Solution Title	Incorrect adjustable parameter setting
Update Reason	Solution Modified
Date	31-Mar-2024
Fault Code / Symptom	Black Smoke
Solution Number	S00000554
Solution Title	Air intake system restricted
Update Reason	Solution Reordered
Date	31-Mar-2024
Fault Code / Symptom	Black Smoke
Solution Number	S00000554
Solution Title	Air intake system restricted
Update Reason	Solution Modified
Date	31-Mar-2024
Fault Code / Symptom	Crank No Start
Solution Number	S00000554
Solution Title	Air intake system restricted
Update Reason	Solution Reordered

Date	31-Mar-2024
Fault Code / Symptom	Crank No Start
Solution Number	S00000554
Solution Title	Air intake system restricted
Update Reason	Solution Modified
Date	31-Mar-2024
Fault Code / Symptom	Engine Speed Surges
Solution Number	S00000554
Solution Title	Air intake system restricted
Update Reason	Solution Reordered
Date	31-Mar-2024
Fault Code / Symptom	Engine Speed Surges
Solution Number	S00000554
Solution Title	Air intake system restricted
Update Reason	Solution Modified
Date	31-Mar-2024
Fault Code / Symptom	Engine Stalls/Shutdown
Solution Number	S00000554
Solution Title	Air intake system restricted
Update Reason	Solution Reordered
Date	31-Mar-2024
Fault Code / Symptom	Engine Stalls/Shutdown
Solution Number	S00000554
Solution Title	Air intake system restricted
Update Reason	Solution Modified
Date	31-Mar-2024
Fault Code / Symptom	Exhaust Temperature High
Solution Number	S00000554
Solution Title	Air intake system restricted
Update Reason	Solution Reordered

Date	31-Mar-2024
Fault Code / Symptom	Exhaust Temperature High
Solution Number	S00000554
Solution Title	Air intake system restricted
Update Reason	Solution Modified
Date	31-Mar-2024
Fault Code / Symptom	Fuel Consumption Excessive
Solution Number	S00000554
Solution Title	Air intake system restricted
Update Reason	Solution Reordered
Date	31-Mar-2024
Fault Code / Symptom	Fuel Consumption Excessive
Solution Number	S00000554
Solution Title	Air intake system restricted
Update Reason	Solution Modified
Date	31-Mar-2024
Fault Code / Symptom	Hard Start/Long Crank Time
Solution Number	S00000554
Solution Title	Air intake system restricted
Update Reason	Solution Reordered
Date	31-Mar-2024
Fault Code / Symptom	Hard Start/Long Crank Time
Solution Number	S00000554
Solution Title	Air intake system restricted
Update Reason	Solution Modified
Date	31-Mar-2024
Fault Code / Symptom	Low Power
Solution Number	S00000554
Solution Title	Air intake system restricted
Update Reason	Solution Reordered

Date	31-Mar-2024
Fault Code / Symptom	Low Power
Solution Number	S00000554
Solution Title	Air intake system restricted
Update Reason	Solution Modified
Date	31-Mar-2024
Fault Code / Symptom	Lubricating Oil in the Air Intake
Solution Number	S00000554
Solution Title	Air intake system restricted
Update Reason	Solution Reordered
Date	31-Mar-2024
Fault Code / Symptom	Lubricating Oil in the Air Intake
Solution Number	S00000554
Solution Title	Air intake system restricted
Update Reason	Solution Modified
Date	31-Mar-2024
Fault Code / Symptom	Turbocharger Compressor Seal Leaking Oil
Solution Number	S00000554
Solution Title	Air intake system restricted
Update Reason	Solution Reordered
Date	31-Mar-2024
Fault Code / Symptom	Turbocharger Compressor Seal Leaking Oil
Solution Number	S00000554
Solution Title	Air intake system restricted
Update Reason	Solution Modified
Date	31-Mar-2024
Fault Code / Symptom	Turbocharger Noise
Solution Number	S00000554
Solution Title	Air intake system restricted
Update Reason	Solution Reordered

Date	31-Mar-2024
Fault Code / Symptom	Turbocharger Noise
Solution Number	S00000554
Solution Title	Air intake system restricted
Update Reason	Solution Modified
Date	31-Mar-2024
Fault Code / Symptom	Turbocharger Turbine Seal Leaking Oil
Solution Number	S00000554
Solution Title	Air intake system restricted
Update Reason	Solution Reordered
Date	31-Mar-2024
Fault Code / Symptom	Turbocharger Turbine Seal Leaking Oil
Solution Number	S00000554
Solution Title	Air intake system restricted
Update Reason	Solution Modified
Date	17-Mar-2024
Fault Code / Symptom	Engine Protection Torque Derate - Condition Exists
Solution Number	
Solution Title	
Update Reason	Solution Set Added
Date	04-Feb-2024
Fault Code / Symptom	Lubricating Oil in the Coolant
Solution Number	S00001324
Solution Title	Transmission lubricating oil cooler is malfunctioning
Update Reason	Solution Removed
Date	31-Dec-2023
Fault Code / Symptom	Injector Solenoid Driver 1 Circuit - Current Below Normal or Open Circuit
Solution Number	S00000976
Solution Title	Fuel injector solenoid to engine block ground resistance check
Update Reason	Solution Added

Date	31-Dec-2023
Fault Code / Symptom	Injector Solenoid Driver 1 Circuit - Current Below Normal or Open Circuit
Solution Number	S00003646
Solution Title	Fuel injector solenoid to engine block ground resistance check
Update Reason	Solution Removed

Date	31-Dec-2023
Fault Code / Symptom	Injector Solenoid Driver 5 Circuit - Current Below Normal or Open Circuit
Solution Number	S00000976
Solution Title	Fuel injector solenoid to engine block ground resistance check
Update Reason	Solution Added

Date	31-Dec-2023
Fault Code / Symptom	Injector Solenoid Driver 5 Circuit - Current Below Normal or Open Circuit
Solution Number	S00003646
Solution Title	Fuel injector solenoid to engine block ground resistance check
Update Reason	Solution Removed

Date	31-Dec-2023
Fault Code / Symptom	Injector Solenoid Driver 3 Circuit - Current Below Normal or Open Circuit
Solution Number	S00000976
Solution Title	Fuel injector solenoid to engine block ground resistance check
Update Reason	Solution Added

Date	31-Dec-2023
Fault Code / Symptom	Injector Solenoid Driver 3 Circuit - Current Below Normal or Open Circuit
Solution Number	S00003646
Solution Title	Fuel injector solenoid to engine block ground resistance check
Update Reason	Solution Removed

Date	31-Dec-2023
Fault Code / Symptom	Injector Solenoid Driver 6 Circuit - Current Below Normal or Open Circuit
Solution Number	S00000976
Solution Title	Fuel injector solenoid to engine block ground resistance check
Update Reason	Solution Added

Date	31-Dec-2023
Fault Code / Symptom	Injector Solenoid Driver 6 Circuit - Current Below Normal or Open Circuit
Solution Number	S00003646
Solution Title	Fuel injector solenoid to engine block ground resistance check
Update Reason	Solution Removed

Date	31-Dec-2023
Fault Code / Symptom	Injector Solenoid Driver 2 Circuit - Current Below Normal or Open Circuit
Solution Number	S00000976
Solution Title	Fuel injector solenoid to engine block ground resistance check
Update Reason	Solution Added

Date	31-Dec-2023
Fault Code / Symptom	Injector Solenoid Driver 2 Circuit - Current Below Normal or Open Circuit
Solution Number	S00003646
Solution Title	Fuel injector solenoid to engine block ground resistance check
Update Reason	Solution Removed

Date	31-Dec-2023
Fault Code / Symptom	Injector Solenoid Driver 4 Circuit - Current Below Normal or Open Circuit
Solution Number	S00000976
Solution Title	Fuel injector solenoid to engine block ground resistance check
Update Reason	Solution Added

Date	31-Dec-2023
Fault Code / Symptom	Injector Solenoid Driver 4 Circuit - Current Below Normal or Open Circuit
Solution Number	S00003646
Solution Title	Fuel injector solenoid to engine block ground resistance check
Update Reason	Solution Removed
Date	22-Oct-2023
Fault Code / Symptom	Engine Oil Rifle Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00000462
Solution Title	Contaminated lubricating oil
Update Reason	Solution Reordered
Date	22-Oct-2023
Fault Code / Symptom	Engine Oil Rifle Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00000462
Solution Title	Contaminated lubricating oil
Update Reason	Solution Modified
Date	22-Oct-2023
Fault Code / Symptom	Engine Coolant Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00011548
Solution Title	Malfunctioning cooling fan drive or cooling fan controls
Update Reason	Solution Added
Date	22-Oct-2023
Fault Code / Symptom	Engine Coolant Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00006146
Solution Title	Fan clutch operates incorrectly
Update Reason	Solution Removed

Date	22-Oct-2023
Fault Code / Symptom	Engine Coolant Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00006090
Solution Title	Malfunctioning cooling fan drive or cooling fan controls
Update Reason	Solution Removed
Date	22-Oct-2023
Fault Code / Symptom	Intake Manifold 1 Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00011548
Solution Title	Malfunctioning cooling fan drive or cooling fan controls
Update Reason	Solution Added
Date	22-Oct-2023
Fault Code / Symptom	Intake Manifold 1 Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00006090
Solution Title	Malfunctioning cooling fan drive or cooling fan controls
Update Reason	Solution Removed
Date	22-Oct-2023
Fault Code / Symptom	Engine Oil Rifle Pressure - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00000462
Solution Title	Contaminated lubricating oil
Update Reason	Solution Reordered

Date	22-Oct-2023
Fault Code / Symptom	Engine Oil Rifle Pressure - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00000462
Solution Title	Contaminated lubricating oil
Update Reason	Solution Modified
Date	03-Sep-2023
Fault Code / Symptom	Coolant Level - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000727
Solution Title	Coolant level sensor voltage check
Update Reason	Solution Removed
Date	03-Sep-2023
Fault Code / Symptom	Coolant Level - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000815
Solution Title	Coolant level sensor circuit check
Update Reason	Solution Removed
Date	30-Jul-2023
Fault Code / Symptom	Accelerator Pedal or Lever Position Sensor Supply Voltage Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	
Solution Title	
Update Reason	Solution Set Added
Date	09-Jul-2023
Fault Code / Symptom	Fuel Consumption Excessive
Solution Number	S00002762
Solution Title	Fluorescent Dye Tracer Test (fuel)
Update Reason	Solution Reordered

Date	09-Jul-2023
Fault Code / Symptom	Fuel Consumption Excessive
Solution Number	S00002762
Solution Title	Fluorescent Dye Tracer Test (fuel)
Update Reason	Solution Modified
Date	09-Jul-2023
Fault Code / Symptom	Fuel in the Lubricating Oil
Solution Number	S00002762
Solution Title	Fluorescent Dye Tracer Test (fuel)
Update Reason	Solution Reordered
Date	09-Jul-2023
Fault Code / Symptom	Fuel in the Lubricating Oil
Solution Number	S00002762
Solution Title	Fluorescent Dye Tracer Test (fuel)
Update Reason	Solution Modified
Date	09-Jul-2023
Fault Code / Symptom	Lubricating Oil Filter Plugging
Solution Number	S00002762
Solution Title	Fluorescent Dye Tracer Test (fuel)
Update Reason	Solution Reordered
Date	09-Jul-2023
Fault Code / Symptom	Lubricating Oil Filter Plugging
Solution Number	S00002762
Solution Title	Fluorescent Dye Tracer Test (fuel)
Update Reason	Solution Modified
Date	09-Jul-2023
Fault Code / Symptom	Lubricating Oil Level High
Solution Number	S00002762
Solution Title	Fluorescent Dye Tracer Test (fuel)
Update Reason	Solution Reordered

Date	09-Jul-2023
Fault Code / Symptom	Lubricating Oil Level High
Solution Number	S00002762
Solution Title	Fluorescent Dye Tracer Test (fuel)
Update Reason	Solution Modified
Date	18-Jun-2023
Fault Code / Symptom	Crank No Start
Solution Number	S00001276
Solution Title	Crankshaft/camshaft sensor
Update Reason	Solution Reordered
Date	18-Jun-2023
Fault Code / Symptom	Crank No Start
Solution Number	S00001276
Solution Title	Crankshaft/camshaft sensor
Update Reason	Solution Modified
Date	11-Jun-2023
Fault Code / Symptom	Engine Control Module Warning Internal Hardware Failure - Bad Intelligent Device or Component
Solution Number	S00008831
Solution Title	ECM Malfunction
Update Reason	Solution Removed
Date	30-Apr-2023
Fault Code / Symptom	Engine Control Module Warning Internal Hardware Failure - Bad Intelligent Device or Component
Solution Number	S00008831
Solution Title	ECM Malfunction
Update Reason	Solution Added
Date	23-Apr-2023
Fault Code / Symptom	Engine Control Module Critical Internal Failure - Bad Intelligent Device or Component
Solution Number	S00008831
Solution Title	ECM Malfunction
Update Reason	Solution Reordered

Date	23-Apr-2023
Fault Code / Symptom	Engine Control Module Critical Internal Failure - Bad Intelligent Device or Component
Solution Number	S00008831
Solution Title	ECM Malfunction
Update Reason	Solution Modified
Date	02-Apr-2023
Fault Code / Symptom	Engine Oil Rifle Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00001453
Solution Title	Main lubricating oil pressure regulator is malfunctioning
Update Reason	Solution Removed
Date	26-Mar-2023
Fault Code / Symptom	Blue Smoke
Solution Number	S00005035
Solution Title	Worn or damaged power cylinder components
Update Reason	Solution Removed
Date	26-Mar-2023
Fault Code / Symptom	Engine Knock
Solution Number	S00001332
Solution Title	Cylinder head gasket or cylinder head is malfunctioning
Update Reason	Solution Reordered
Date	26-Mar-2023
Fault Code / Symptom	Engine Knock
Solution Number	S00001332
Solution Title	Cylinder head gasket or cylinder head is malfunctioning
Update Reason	Solution Modified

Date	26-Mar-2023
Fault Code / Symptom	Exhaust Noise
Solution Number	S00001332
Solution Title	Cylinder head gasket or cylinder head is malfunctioning
Update Reason	Solution Reordered
Date	26-Mar-2023
Fault Code / Symptom	Exhaust Noise
Solution Number	S00001332
Solution Title	Cylinder head gasket or cylinder head is malfunctioning
Update Reason	Solution Modified
Date	26-Mar-2023
Fault Code / Symptom	High Blowby
Solution Number	S00005035
Solution Title	Worn or damaged power cylinder components
Update Reason	Solution Removed
Date	26-Mar-2023
Fault Code / Symptom	No Communication with the Cummins Electronic Service Tool or Equivalent to ECM
Solution Number	S00011256
Solution Title	Unswitched battery open circuit check
Update Reason	Solution Added
Date	05-Mar-2023
Fault Code / Symptom	Engine Magnetic Crankshaft Speed/Position Lost One of Two Signals - Abnormal Rate of Change
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	26-Feb-2023
Fault Code / Symptom	Black Smoke
Solution Number	S00009619
Solution Title	Charge air cooler system leak
Update Reason	Solution Added

Date	26-Feb-2023
Fault Code / Symptom	Engine Speed Surges
Solution Number	S00009619
Solution Title	Charge air cooler system leak
Update Reason	Solution Added
Date	26-Feb-2023
Fault Code / Symptom	Fuel Consumption Excessive
Solution Number	S00009619
Solution Title	Charge air cooler system leak
Update Reason	Solution Added
Date	26-Feb-2023
Fault Code / Symptom	Low Power
Solution Number	S00009619
Solution Title	Charge air cooler system leak
Update Reason	Solution Added
Date	26-Feb-2023
Fault Code / Symptom	Turbocharger Noise
Solution Number	S00009619
Solution Title	Charge air cooler system leak
Update Reason	Solution Added
Date	20-Feb-2023
Fault Code / Symptom	Air Compressor Continuous Operation/Frequent Cycling
Solution Number	S00010920
Solution Title	Air compressor cylinder head assembly system is malfunctioning
Update Reason	Solution Added
Date	20-Feb-2023
Fault Code / Symptom	Air Compressor Continuous Operation/Frequent Cycling
Solution Number	S00010921
Solution Title	Air compressor cylinder head cleaning (ST model)
Update Reason	Solution Added

Date	20-Feb-2023
Fault Code / Symptom	Air Compressor Continuous Operation/Frequent Cycling
Solution Number	S00010922
Solution Title	Air compressor cylinder head cleaning (QE model)
Update Reason	Solution Added
Date	20-Feb-2023
Fault Code / Symptom	Air Compressor Continuous Operation/Frequent Cycling
Solution Number	S00010923
Solution Title	Air compressor cylinder head cleaning (SS and E-type model)
Update Reason	Solution Added
Date	20-Feb-2023
Fault Code / Symptom	Air Compressor Continuous Operation/Frequent Cycling
Solution Number	S00001050
Solution Title	Air compressor cylinder head assembly system is malfunctioning
Update Reason	Solution Removed
Date	20-Feb-2023
Fault Code / Symptom	Air Compressor Continuous Operation/Frequent Cycling
Solution Number	S00001047
Solution Title	On-engine air compressor cleaning
Update Reason	Solution Removed
Date	20-Feb-2023
Fault Code / Symptom	Air Compressor Continuous Operation/Frequent Cycling
Solution Number	S00001069
Solution Title	Off-engine air compressor cleaning
Update Reason	Solution Removed

Date	20-Feb-2023
Fault Code / Symptom	Air Compressor Will Not Pump Air
Solution Number	S00010920
Solution Title	Air compressor cylinder head assembly system is malfunctioning
Update Reason	Solution Added
Date	20-Feb-2023
Fault Code / Symptom	Air Compressor Will Not Pump Air
Solution Number	S00010921
Solution Title	Air compressor cylinder head cleaning (ST model)
Update Reason	Solution Added
Date	20-Feb-2023
Fault Code / Symptom	Air Compressor Will Not Pump Air
Solution Number	S00010922
Solution Title	Air compressor cylinder head cleaning (QE model)
Update Reason	Solution Added
Date	20-Feb-2023
Fault Code / Symptom	Air Compressor Will Not Pump Air
Solution Number	S00010923
Solution Title	Air compressor cylinder head cleaning (SS and E-type model)
Update Reason	Solution Added
Date	20-Feb-2023
Fault Code / Symptom	Air Compressor Will Not Pump Air
Solution Number	S00001050
Solution Title	Air compressor cylinder head assembly system is malfunctioning
Update Reason	Solution Removed
Date	20-Feb-2023
Fault Code / Symptom	Air Compressor Will Not Pump Air
Solution Number	S00001047
Solution Title	On-engine air compressor cleaning
Update Reason	Solution Removed

Date	20-Feb-2023
Fault Code / Symptom	Air Compressor Will Not Pump Air
Solution Number	S00001069
Solution Title	Off-engine air compressor cleaning
Update Reason	Solution Removed
Date	05-Feb-2023
Fault Code / Symptom	External Lubricating Oil Leak
Solution Number	S00011119
Solution Title	Plugged crankcase breather component (internal)
Update Reason	Solution Added
Date	05-Feb-2023
Fault Code / Symptom	Lubricating Oil in the Air Intake
Solution Number	S00011119
Solution Title	Plugged crankcase breather component (internal)
Update Reason	Solution Added
Date	05-Feb-2023
Fault Code / Symptom	Turbocharger Compressor Seal Leaking Oil
Solution Number	S00011119
Solution Title	Plugged crankcase breather component (internal)
Update Reason	Solution Added
Date	15-Jan-2023
Fault Code / Symptom	Engine Stalls/Shutdown
Solution Number	S00001200
Solution Title	Battery or battery cables are malfunctioning
Update Reason	Solution Removed
Date	01-Jan-2023
Fault Code / Symptom	Coolant Temperature High
Solution Number	S00011070
Solution Title	Fan control solenoid air line is malfunctioning
Update Reason	Solution Added

Date	01-Jan-2023
Fault Code / Symptom	Coolant Temperature Low
Solution Number	S00011070
Solution Title	Fan control solenoid air line is malfunctioning
Update Reason	Solution Added
Date	01-Jan-2023
Fault Code / Symptom	Fan Not Running/Erratic Running
Solution Number	S00011070
Solution Title	Fan control solenoid air line is malfunctioning
Update Reason	Solution Added
Date	01-Jan-2023
Fault Code / Symptom	Fan Runs Continuously/Excessive Operation
Solution Number	S00011070
Solution Title	Fan control solenoid air line is malfunctioning
Update Reason	Solution Added
Date	01-Jan-2023
Fault Code / Symptom	Engine Coolant Temperature 1 Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000127
Solution Title	Coolant temperature sensor resistance check
Update Reason	Solution Removed
Date	01-Jan-2023
Fault Code / Symptom	Engine Coolant Temperature 1 Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000127
Solution Title	Coolant temperature sensor resistance check
Update Reason	Solution Removed
Date	20-Nov-2022
Fault Code / Symptom	No Communication with the Cummins Electronic Service Tool or Equivalent to ECM
Solution Number	S00000877
Solution Title	Wiring harness load test
Update Reason	Solution Removed

Date	13-Nov-2022
Fault Code / Symptom	Air Compressor Continuous Operation/Frequent Cycling
Solution Number	S00011047
Solution Title	Air intake system restricted
Update Reason	Solution Added
Date	13-Nov-2022
Fault Code / Symptom	Air Compressor Continuous Operation/Frequent Cycling
Solution Number	S00000554
Solution Title	Restricted intake air filter
Update Reason	Solution Removed
Date	13-Nov-2022
Fault Code / Symptom	Air Compressor Pumping Lubricating Oil
Solution Number	S00011047
Solution Title	Air intake system restricted
Update Reason	Solution Added
Date	13-Nov-2022
Fault Code / Symptom	Air Compressor Pumping Lubricating Oil
Solution Number	S00000554
Solution Title	Restricted intake air filter
Update Reason	Solution Removed
Date	13-Nov-2022
Fault Code / Symptom	Air Compressor Will Not Pump Air
Solution Number	S00011047
Solution Title	Air intake system restricted
Update Reason	Solution Added
Date	13-Nov-2022
Fault Code / Symptom	Air Compressor Will Not Pump Air
Solution Number	S00000554
Solution Title	Restricted intake air filter
Update Reason	Solution Removed

Date	13-Nov-2022
Fault Code / Symptom	Engine Control Module Warning Internal Hardware Failure - Bad Intelligent Device or Component
Solution Number	S00001622
Solution Title	ECM Malfunction
Update Reason	Solution Removed
Date	13-Nov-2022
Fault Code / Symptom	Engine Brake Actuator Driver 1 Circuit - Root Cause Not Known
Solution Number	S00001622
Solution Title	ECM Malfunction
Update Reason	Solution Removed
Date	13-Nov-2022
Fault Code / Symptom	Engine Brake Actuator Driver 2 Circuit - Root Cause Not Known
Solution Number	S00001622
Solution Title	ECM Malfunction
Update Reason	Solution Removed
Date	30-Oct-2022
Fault Code / Symptom	Engine Coolant Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	
Solution Title	
Update Reason	Solution Set Added
Date	16-Oct-2022
Fault Code / Symptom	Engine Knock
Solution Number	S00001344
Solution Title	Air compressor timing incorrect
Update Reason	Solution Removed

Date	09-Oct-2022
Fault Code / Symptom	No Communication ECM to Component
Solution Number	S00010993
Solution Title	Low battery voltage
Update Reason	Solution Added
Date	09-Oct-2022
Fault Code / Symptom	No Communication ECM to Component
Solution Number	S00001379
Solution Title	Battery load test
Update Reason	Solution Added
Date	09-Oct-2022
Fault Code / Symptom	No Communication ECM to Component
Solution Number	S00000754
Solution Title	Ground inspection
Update Reason	Solution Added
Date	09-Oct-2022
Fault Code / Symptom	No Communication with the Cummins Electronic Service Tool or Equivalent to ECM
Solution Number	S00010993
Solution Title	Low battery voltage
Update Reason	Solution Added
Date	09-Oct-2022
Fault Code / Symptom	No Communication with the Cummins Electronic Service Tool or Equivalent to ECM
Solution Number	S00001379
Solution Title	Battery load test
Update Reason	Solution Added
Date	09-Oct-2022
Fault Code / Symptom	No Communication with the Cummins Electronic Service Tool or Equivalent to ECM
Solution Number	S00000754
Solution Title	Ground inspection
Update Reason	Solution Added

Date	02-Oct-2022
Fault Code / Symptom	Cranks Slowly
Solution Number	S00001224
Solution Title	Crankshaft rotation is restricted
Update Reason	Solution Reordered
Date	02-Oct-2022
Fault Code / Symptom	Cranks Slowly
Solution Number	S00001224
Solution Title	Crankshaft rotation is restricted
Update Reason	Solution Modified
Date	02-Oct-2022
Fault Code / Symptom	Will Not Crank
Solution Number	S00001224
Solution Title	Crankshaft rotation is restricted
Update Reason	Solution Reordered
Date	02-Oct-2022
Fault Code / Symptom	Will Not Crank
Solution Number	S00001224
Solution Title	Crankshaft rotation is restricted
Update Reason	Solution Modified
Date	02-Oct-2022
Fault Code / Symptom	Will Not Crank
Solution Number	S00000898
Solution Title	Starter magnetic switch is malfunctioning
Update Reason	Solution Reordered
Date	02-Oct-2022
Fault Code / Symptom	Will Not Crank
Solution Number	S00000898
Solution Title	Starter magnetic switch is malfunctioning
Update Reason	Solution Modified

Date	02-Oct-2022
Fault Code / Symptom	Auxiliary Temperature Sensor Input 1 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000833
Solution Title	Ambient air temperature sensor open circuit check
Update Reason	Solution Removed
Date	25-Sep-2022
Fault Code / Symptom	External Speed Command Input (Multiple Unit Synchronization) - Data Erratic, Intermittent, or Incorrect
Solution Number	
Solution Title	
Update Reason	Solution Set Added
Date	11-Sep-2022
Fault Code / Symptom	Engine Brake Actuator Driver 1 Circuit - Root Cause Not Known
Solution Number	S00002799
Solution Title	Engine brake solenoid valve resistance check
Update Reason	Solution Added
Date	11-Sep-2022
Fault Code / Symptom	Engine Brake Actuator Driver 2 Circuit - Root Cause Not Known
Solution Number	S00002799
Solution Title	Engine brake solenoid valve resistance check
Update Reason	Solution Added
Date	11-Sep-2022
Fault Code / Symptom	Engine Brake Actuator Driver 2 Circuit - Root Cause Not Known
Solution Number	S00001031
Solution Title	Engine brake solenoid valve resistance check
Update Reason	Solution Removed

Date	24-Jul-2022
Fault Code / Symptom	Intake Manifold 1 Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00006090
Solution Title	Malfunctioning cooling fan drive or cooling fan controls
Update Reason	Solution Added
Date	24-Jul-2022
Fault Code / Symptom	Intake Manifold 1 Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00000490
Solution Title	Malfunctioning cooling fan drive or cooling fan controls
Update Reason	Solution Removed
Date	28-Jun-2022
Fault Code / Symptom	Engine Protection Torque Derate - Condition Exists
Solution Number	
Solution Title	
Update Reason	Solution Set Removed
Date	12-Jun-2022
Fault Code / Symptom	Transmission Output Shaft Speed - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	
Solution Title	
Update Reason	Solution Set Removed
Date	12-Jun-2022
Fault Code / Symptom	J1939 Network #1 - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000902
Solution Title	Incorrect adjustable parameter setting
Update Reason	Solution Added

Date	12-Jun-2022
Fault Code / Symptom	J1939 Network #1 - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000443
Solution Title	ECM calibration revision history check
Update Reason	Solution Added
Date	05-Jun-2022
Fault Code / Symptom	Fuel in the Coolant
Solution Number	
Solution Title	
Update Reason	Solution Set Added
Date	05-Jun-2022
Fault Code / Symptom	Coolant in the Lubricating Oil
Solution Number	S00003469
Solution Title	Fuel injector o-rings or fuel injector sleeves are damaged
Update Reason	Solution Removed
Date	05-Jun-2022
Fault Code / Symptom	Internal Coolant Leak
Solution Number	S00003469
Solution Title	Fuel injector o-rings or fuel injector sleeves are damaged
Update Reason	Solution Removed
Date	05-Jun-2022
Fault Code / Symptom	White Smoke
Solution Number	S00003469
Solution Title	Fuel injector o-rings or fuel injector sleeves are damaged
Update Reason	Solution Removed
Date	29-May-2022
Fault Code / Symptom	Engine Stalls/Shutdown
Solution Number	S00002742
Solution Title	Fuel shutoff valve is malfunctioning
Update Reason	Solution Reordered

Date	29-May-2022
Fault Code / Symptom	Engine Stalls/Shutdown
Solution Number	S00002742
Solution Title	Fuel shutoff valve is malfunctioning
Update Reason	Solution Modified
Date	29-May-2022
Fault Code / Symptom	Hard Start/Long Crank Time
Solution Number	S00002742
Solution Title	Fuel shutoff valve is malfunctioning
Update Reason	Solution Reordered
Date	29-May-2022
Fault Code / Symptom	Hard Start/Long Crank Time
Solution Number	S00002742
Solution Title	Fuel shutoff valve is malfunctioning
Update Reason	Solution Modified
Date	08-May-2022
Fault Code / Symptom	Coolant Level Low
Solution Number	
Solution Title	
Update Reason	Solution Set Removed
Date	17-Apr-2022
Fault Code / Symptom	Coolant Level - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00010538
Solution Title	Coolant level check
Update Reason	Solution Added
Date	17-Apr-2022
Fault Code / Symptom	Coolant Level - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00007852
Solution Title	Missing or damaged coolant level sensor
Update Reason	Solution Removed

Date	17-Apr-2022
Fault Code / Symptom	Coolant Level - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00002155
Solution Title	Cooling system component is leaking
Update Reason	Solution Removed
Date	17-Apr-2022
Fault Code / Symptom	Injector Solenoid Driver 1 Circuit - Current Below Normal or Open Circuit
Solution Number	S00004294
Solution Title	Check for primary fault codes
Update Reason	Solution Added
Date	17-Apr-2022
Fault Code / Symptom	Injector Solenoid Driver 1 Circuit - Current Below Normal or Open Circuit
Solution Number	S00001527
Solution Title	Check for primary fault codes
Update Reason	Solution Removed
Date	17-Apr-2022
Fault Code / Symptom	Injector Solenoid Driver 5 Circuit - Current Below Normal or Open Circuit
Solution Number	S00004294
Solution Title	Check for primary fault codes
Update Reason	Solution Added
Date	17-Apr-2022
Fault Code / Symptom	Injector Solenoid Driver 5 Circuit - Current Below Normal or Open Circuit
Solution Number	S00001527
Solution Title	Check for primary fault codes
Update Reason	Solution Removed

Date	17-Apr-2022
Fault Code / Symptom	Injector Solenoid Driver 3 Circuit - Current Below Normal or Open Circuit
Solution Number	S00004294
Solution Title	Check for primary fault codes
Update Reason	Solution Added

Date	17-Apr-2022
Fault Code / Symptom	Injector Solenoid Driver 3 Circuit - Current Below Normal or Open Circuit
Solution Number	S00001527
Solution Title	Check for primary fault codes
Update Reason	Solution Removed

Date	17-Apr-2022
Fault Code / Symptom	Injector Solenoid Driver 6 Circuit - Current Below Normal or Open Circuit
Solution Number	S00004294
Solution Title	Check for primary fault codes
Update Reason	Solution Added

Date	17-Apr-2022
Fault Code / Symptom	Injector Solenoid Driver 6 Circuit - Current Below Normal or Open Circuit
Solution Number	S00001527
Solution Title	Check for primary fault codes
Update Reason	Solution Removed

Date	17-Apr-2022
Fault Code / Symptom	Injector Solenoid Driver 2 Circuit - Current Below Normal or Open Circuit
Solution Number	S00004294
Solution Title	Check for primary fault codes
Update Reason	Solution Added

Date	17-Apr-2022
Fault Code / Symptom	Injector Solenoid Driver 2 Circuit - Current Below Normal or Open Circuit
Solution Number	S00001527
Solution Title	Check for primary fault codes
Update Reason	Solution Removed
Date	17-Apr-2022
Fault Code / Symptom	Injector Solenoid Driver 4 Circuit - Current Below Normal or Open Circuit
Solution Number	S00004294
Solution Title	Check for primary fault codes
Update Reason	Solution Added
Date	17-Apr-2022
Fault Code / Symptom	Injector Solenoid Driver 4 Circuit - Current Below Normal or Open Circuit
Solution Number	S00001527
Solution Title	Check for primary fault codes
Update Reason	Solution Removed
Date	17-Apr-2022
Fault Code / Symptom	Coolant Level - Data Erratic, Intermittent, or Incorrect
Solution Number	S00010538
Solution Title	Coolant level check
Update Reason	Solution Added
Date	17-Apr-2022
Fault Code / Symptom	Coolant Level - Data Erratic, Intermittent, or Incorrect
Solution Number	S00007852
Solution Title	Missing or damaged coolant level sensor
Update Reason	Solution Removed

Date	17-Apr-2022
Fault Code / Symptom	Coolant Level - Data Erratic, Intermittent, or Incorrect
Solution Number	S00002155
Solution Title	Cooling system component is leaking
Update Reason	Solution Removed
Date	10-Apr-2022
Fault Code / Symptom	Cylinder Power Imbalance Between Cylinders - Data Erratic, Intermittent, or Incorrect
Solution Number	S00002160
Solution Title	Cylinder Cutout Test
Update Reason	Solution Reordered
Date	10-Apr-2022
Fault Code / Symptom	Cylinder Power Imbalance Between Cylinders - Data Erratic, Intermittent, or Incorrect
Solution Number	S00002160
Solution Title	Cylinder Cutout Test
Update Reason	Solution Modified
Date	03-Apr-2022
Fault Code / Symptom	Coolant Level - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00010587
Solution Title	Check for primary fault codes
Update Reason	Solution Added
Date	03-Apr-2022
Fault Code / Symptom	Coolant Level - Data Erratic, Intermittent, or Incorrect
Solution Number	S00010587
Solution Title	Check for primary fault codes
Update Reason	Solution Added

Date	27-Mar-2022
Fault Code / Symptom	Engine Magnetic Speed/Position Lost Both of Two Signals - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000451
Solution Title	Battery or battery cables are malfunctioning
Update Reason	Solution Reordered
Date	27-Mar-2022
Fault Code / Symptom	Engine Magnetic Speed/Position Lost Both of Two Signals - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000451
Solution Title	Battery or battery cables are malfunctioning
Update Reason	Solution Modified
Date	27-Mar-2022
Fault Code / Symptom	Engine Control Module Warning Internal Hardware Failure - Bad Intelligent Device or Component
Solution Number	S00000451
Solution Title	Battery or battery cables are malfunctioning
Update Reason	Solution Reordered
Date	27-Mar-2022
Fault Code / Symptom	Engine Control Module Warning Internal Hardware Failure - Bad Intelligent Device or Component
Solution Number	S00000451
Solution Title	Battery or battery cables are malfunctioning
Update Reason	Solution Modified
Date	27-Mar-2022
Fault Code / Symptom	Power Supply Lost With Ignition On - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000706
Solution Title	Battery power removed by battery disconnect switch
Update Reason	Solution Reordered

Date	27-Mar-2022
Fault Code / Symptom	Power Supply Lost With Ignition On - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000706
Solution Title	Battery power removed by battery disconnect switch
Update Reason	Solution Modified
Date	27-Mar-2022
Fault Code / Symptom	Power Supply Lost With Ignition On - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000451
Solution Title	Battery or battery cables are malfunctioning
Update Reason	Solution Reordered
Date	27-Mar-2022
Fault Code / Symptom	Power Supply Lost With Ignition On - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000451
Solution Title	Battery or battery cables are malfunctioning
Update Reason	Solution Modified
Date	27-Mar-2022
Fault Code / Symptom	Battery 1 Voltage - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00000451
Solution Title	Battery or battery cables are malfunctioning
Update Reason	Solution Reordered
Date	27-Mar-2022
Fault Code / Symptom	Battery 1 Voltage - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00000451
Solution Title	Battery or battery cables are malfunctioning
Update Reason	Solution Modified

Date	27-Mar-2022
Fault Code / Symptom	Battery 1 Voltage - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000451
Solution Title	Battery or battery cables are malfunctioning
Update Reason	Solution Reordered

Date	27-Mar-2022
Fault Code / Symptom	Battery 1 Voltage - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000451
Solution Title	Battery or battery cables are malfunctioning
Update Reason	Solution Modified

Date	27-Mar-2022
Fault Code / Symptom	Electrical Charging System Voltage - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000451
Solution Title	Battery or battery cables are malfunctioning
Update Reason	Solution Reordered

Date	27-Mar-2022
Fault Code / Symptom	Electrical Charging System Voltage - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000451
Solution Title	Battery or battery cables are malfunctioning
Update Reason	Solution Modified

Date	27-Mar-2022
Fault Code / Symptom	Electrical Charging System Voltage - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00000451
Solution Title	Battery or battery cables are malfunctioning
Update Reason	Solution Reordered

Date	27-Mar-2022
Fault Code / Symptom	Electrical Charging System Voltage - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00000451
Solution Title	Battery or battery cables are malfunctioning
Update Reason	Solution Modified
Date	27-Mar-2022
Fault Code / Symptom	Electrical Charging System Voltage - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00000451
Solution Title	Battery or battery cables are malfunctioning
Update Reason	Solution Reordered
Date	27-Mar-2022
Fault Code / Symptom	Electrical Charging System Voltage - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00000451
Solution Title	Battery or battery cables are malfunctioning
Update Reason	Solution Modified
Date	20-Mar-2022
Fault Code / Symptom	Air Compressor Continuous Operation/Frequent Cycling
Solution Number	S00000554
Solution Title	Restricted intake air filter
Update Reason	Solution Reordered
Date	20-Mar-2022
Fault Code / Symptom	Air Compressor Continuous Operation/Frequent Cycling
Solution Number	S00000554
Solution Title	Restricted intake air filter
Update Reason	Solution Modified

Date	20-Mar-2022
Fault Code / Symptom	Air Compressor Pumping Lubricating Oil
Solution Number	S00000554
Solution Title	Restricted intake air filter
Update Reason	Solution Reordered
Date	20-Mar-2022
Fault Code / Symptom	Air Compressor Pumping Lubricating Oil
Solution Number	S00000554
Solution Title	Restricted intake air filter
Update Reason	Solution Modified
Date	20-Mar-2022
Fault Code / Symptom	Air Compressor Will Not Pump Air
Solution Number	S00000554
Solution Title	Restricted intake air filter
Update Reason	Solution Reordered
Date	20-Mar-2022
Fault Code / Symptom	Air Compressor Will Not Pump Air
Solution Number	S00000554
Solution Title	Restricted intake air filter
Update Reason	Solution Modified
Date	20-Mar-2022
Fault Code / Symptom	Black Smoke
Solution Number	S00000554
Solution Title	Restricted intake air filter
Update Reason	Solution Reordered
Date	20-Mar-2022
Fault Code / Symptom	Black Smoke
Solution Number	S00000554
Solution Title	Restricted intake air filter
Update Reason	Solution Modified

Date	20-Mar-2022
Fault Code / Symptom	Crank No Start
Solution Number	S00000554
Solution Title	Restricted intake air filter
Update Reason	Solution Reordered
Date	20-Mar-2022
Fault Code / Symptom	Crank No Start
Solution Number	S00000554
Solution Title	Restricted intake air filter
Update Reason	Solution Modified
Date	20-Mar-2022
Fault Code / Symptom	Engine Speed Surges
Solution Number	S00000554
Solution Title	Restricted intake air filter
Update Reason	Solution Reordered
Date	20-Mar-2022
Fault Code / Symptom	Engine Speed Surges
Solution Number	S00000554
Solution Title	Restricted intake air filter
Update Reason	Solution Modified
Date	20-Mar-2022
Fault Code / Symptom	Engine Stalls/Shutdown
Solution Number	S00000554
Solution Title	Restricted intake air filter
Update Reason	Solution Reordered
Date	20-Mar-2022
Fault Code / Symptom	Engine Stalls/Shutdown
Solution Number	S00000554
Solution Title	Restricted intake air filter
Update Reason	Solution Modified

Date	20-Mar-2022
Fault Code / Symptom	Exhaust Temperature High
Solution Number	S00000554
Solution Title	Restricted intake air filter
Update Reason	Solution Reordered
Date	20-Mar-2022
Fault Code / Symptom	Exhaust Temperature High
Solution Number	S00000554
Solution Title	Restricted intake air filter
Update Reason	Solution Modified
Date	20-Mar-2022
Fault Code / Symptom	Fuel Consumption Excessive
Solution Number	S00000554
Solution Title	Restricted intake air filter
Update Reason	Solution Reordered
Date	20-Mar-2022
Fault Code / Symptom	Fuel Consumption Excessive
Solution Number	S00000554
Solution Title	Restricted intake air filter
Update Reason	Solution Modified
Date	20-Mar-2022
Fault Code / Symptom	Hard Start/Long Crank Time
Solution Number	S00000554
Solution Title	Restricted intake air filter
Update Reason	Solution Reordered
Date	20-Mar-2022
Fault Code / Symptom	Hard Start/Long Crank Time
Solution Number	S00000554
Solution Title	Restricted intake air filter
Update Reason	Solution Modified

Date	20-Mar-2022
Fault Code / Symptom	Low Power
Solution Number	S00000554
Solution Title	Restricted intake air filter
Update Reason	Solution Reordered
Date	20-Mar-2022
Fault Code / Symptom	Low Power
Solution Number	S00000554
Solution Title	Restricted intake air filter
Update Reason	Solution Modified
Date	20-Mar-2022
Fault Code / Symptom	Lubricating Oil in the Air Intake
Solution Number	S00000554
Solution Title	Restricted intake air filter
Update Reason	Solution Reordered
Date	20-Mar-2022
Fault Code / Symptom	Lubricating Oil in the Air Intake
Solution Number	S00000554
Solution Title	Restricted intake air filter
Update Reason	Solution Modified
Date	20-Mar-2022
Fault Code / Symptom	Turbocharger Compressor Seal Leaking Oil
Solution Number	S00000554
Solution Title	Restricted intake air filter
Update Reason	Solution Reordered
Date	20-Mar-2022
Fault Code / Symptom	Turbocharger Compressor Seal Leaking Oil
Solution Number	S00000554
Solution Title	Restricted intake air filter
Update Reason	Solution Modified

Date	20-Mar-2022
Fault Code / Symptom	Turbocharger Noise
Solution Number	S00000554
Solution Title	Restricted intake air filter
Update Reason	Solution Reordered
Date	20-Mar-2022
Fault Code / Symptom	Turbocharger Noise
Solution Number	S00000554
Solution Title	Restricted intake air filter
Update Reason	Solution Modified
Date	20-Mar-2022
Fault Code / Symptom	Turbocharger Turbine Seal Leaking Oil
Solution Number	S00000554
Solution Title	Restricted intake air filter
Update Reason	Solution Reordered
Date	20-Mar-2022
Fault Code / Symptom	Turbocharger Turbine Seal Leaking Oil
Solution Number	S00000554
Solution Title	Restricted intake air filter
Update Reason	Solution Modified
Date	20-Mar-2022
Fault Code / Symptom	Engine Fuel Shutoff Valve Driver Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00003449
Solution Title	Fuel shutoff valve is malfunctioning
Update Reason	Solution Added
Date	20-Mar-2022
Fault Code / Symptom	Engine Fuel Shutoff Valve Driver Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00003700
Solution Title	Fuel shutoff valve is malfunctioning
Update Reason	Solution Removed

Date	20-Mar-2022
Fault Code / Symptom	Engine Fuel Shutoff Valve Driver Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00003449
Solution Title	Fuel shutoff valve is malfunctioning
Update Reason	Solution Added
Date	06-Mar-2022
Fault Code / Symptom	Engine Magnetic Speed/Position Lost Both of Two Signals - Data Erratic, Intermittent, or Incorrect
Solution Number	S00003599
Solution Title	Engine crankshaft speed/position sensor resistance check
Update Reason	Solution Removed
Date	06-Mar-2022
Fault Code / Symptom	Engine Magnetic Crankshaft Speed/Position Lost One of Two Signals - Abnormal Rate of Change
Solution Number	S00010367
Solution Title	Engine position sensor resistance check
Update Reason	Solution Added
Date	06-Mar-2022
Fault Code / Symptom	Engine Magnetic Crankshaft Speed/Position Lost One of Two Signals - Abnormal Rate of Change
Solution Number	S00003599
Solution Title	Engine crankshaft speed/position sensor resistance check
Update Reason	Solution Removed
Date	06-Mar-2022
Fault Code / Symptom	Air Compressor Noise
Solution Number	S00001216
Solution Title	Air compressor damaged or excessively worn
Update Reason	Solution Added

Date	06-Mar-2022
Fault Code / Symptom	Air Compressor Pumping Lubricating Oil
Solution Number	S00001216
Solution Title	Air compressor damaged or excessively worn
Update Reason	Solution Added
Date	06-Mar-2022
Fault Code / Symptom	Engine Magnetic Crankshaft Speed/Position Lost One of Two Signals - Abnormal Rate of Change
Solution Number	S00010361
Solution Title	Engine position sensor open circuit check
Update Reason	Solution Added
Date	06-Mar-2022
Fault Code / Symptom	Engine Magnetic Crankshaft Speed/Position Lost One of Two Signals - Abnormal Rate of Change
Solution Number	S00010362
Solution Title	Engine position sensor circuit pin to ground short
Update Reason	Solution Added
Date	06-Mar-2022
Fault Code / Symptom	Engine Magnetic Crankshaft Speed/Position Lost One of Two Signals - Abnormal Rate of Change
Solution Number	S00010363
Solution Title	Engine position sensor circuit pin to pin short
Update Reason	Solution Added
Date	06-Mar-2022
Fault Code / Symptom	Engine Magnetic Crankshaft Speed/Position Lost One of Two Signals - Abnormal Rate of Change
Solution Number	S00000676
Solution Title	Crankshaft position sensor open circuit check
Update Reason	Solution Removed

Date	06-Mar-2022
Fault Code / Symptom	Engine Magnetic Crankshaft Speed/Position Lost One of Two Signals - Abnormal Rate of Change
Solution Number	S00004444
Solution Title	Crankshaft position sensor circuit pin to ground short
Update Reason	Solution Removed
Date	06-Mar-2022
Fault Code / Symptom	Engine Magnetic Crankshaft Speed/Position Lost One of Two Signals - Abnormal Rate of Change
Solution Number	S00004443
Solution Title	Crankshaft position sensor circuit pin to pin short
Update Reason	Solution Removed
Date	20-Feb-2022
Fault Code / Symptom	Engine Noise
Solution Number	S00009627
Solution Title	Leaks in the intake air system
Update Reason	Solution Added
Date	20-Feb-2022
Fault Code / Symptom	Engine Noise
Solution Number	S00009631
Solution Title	Leaks in the exhaust system
Update Reason	Solution Added
Date	20-Feb-2022
Fault Code / Symptom	Vibration
Solution Number	S00001378
Solution Title	Engine driven accessories damaged
Update Reason	Solution Reordered

Date	20-Feb-2022
Fault Code / Symptom	Vibration
Solution Number	S00001378
Solution Title	Engine driven accessories damaged
Update Reason	Solution Modified
Date	20-Feb-2022
Fault Code / Symptom	Vibration
Solution Number	S00001949
Solution Title	Engine mounts are damaged
Update Reason	Solution Reordered
Date	20-Feb-2022
Fault Code / Symptom	Vibration
Solution Number	S00001949
Solution Title	Engine mounts are damaged
Update Reason	Solution Modified
Date	13-Feb-2022
Fault Code / Symptom	Engine Brake Actuator Driver 2 Circuit - Root Cause Not Known
Solution Number	S00002799
Solution Title	Engine brake solenoid valve resistance check
Update Reason	Solution Removed
Date	30-Jan-2022
Fault Code / Symptom	Air Compressor Noise
Solution Number	S00001268
Solution Title	Air compressor damaged or excessively worn
Update Reason	Solution Reordered
Date	30-Jan-2022
Fault Code / Symptom	Air Compressor Noise
Solution Number	S00001268
Solution Title	Air compressor damaged or excessively worn
Update Reason	Solution Modified

Date	30-Jan-2022
Fault Code / Symptom	Air Compressor Pumping Lubricating Oil
Solution Number	S00001268
Solution Title	Air compressor damaged or excessively worn
Update Reason	Solution Reordered
Date	30-Jan-2022
Fault Code / Symptom	Air Compressor Pumping Lubricating Oil
Solution Number	S00001268
Solution Title	Air compressor damaged or excessively worn
Update Reason	Solution Modified
Date	30-Jan-2022
Fault Code / Symptom	Air Compressor Will Not Pump Air
Solution Number	S00001268
Solution Title	Air compressor damaged or excessively worn
Update Reason	Solution Reordered
Date	30-Jan-2022
Fault Code / Symptom	Air Compressor Will Not Pump Air
Solution Number	S00001268
Solution Title	Air compressor damaged or excessively worn
Update Reason	Solution Modified
Date	09-Jan-2022
Fault Code / Symptom	Belt Fraying/Belt Wear
Solution Number	S00001273
Solution Title	Front end belt driven accessories
Update Reason	Solution Reordered
Date	09-Jan-2022
Fault Code / Symptom	Belt Fraying/Belt Wear
Solution Number	S00001273
Solution Title	Front end belt driven accessories
Update Reason	Solution Modified

Date	09-Jan-2022
Fault Code / Symptom	Belt Noise/Whining
Solution Number	S00001273
Solution Title	Front end belt driven accessories
Update Reason	Solution Reordered
Date	09-Jan-2022
Fault Code / Symptom	Belt Noise/Whining
Solution Number	S00001273
Solution Title	Front end belt driven accessories
Update Reason	Solution Modified
Date	09-Jan-2022
Fault Code / Symptom	Coolant Overflow
Solution Number	S00002071
Solution Title	Cooling system pressure cap is malfunctioning
Update Reason	Solution Reordered
Date	09-Jan-2022
Fault Code / Symptom	Coolant Overflow
Solution Number	S00002071
Solution Title	Cooling system pressure cap is malfunctioning
Update Reason	Solution Modified
Date	09-Jan-2022
Fault Code / Symptom	Engine Noise
Solution Number	S00001273
Solution Title	Front end belt driven accessories
Update Reason	Solution Reordered
Date	09-Jan-2022
Fault Code / Symptom	Engine Noise
Solution Number	S00001273
Solution Title	Front end belt driven accessories
Update Reason	Solution Modified

Date	09-Jan-2022
Fault Code / Symptom	Fan Not Running/Erratic Running
Solution Number	S00001273
Solution Title	Front end belt driven accessories
Update Reason	Solution Reordered
Date	09-Jan-2022
Fault Code / Symptom	Fan Not Running/Erratic Running
Solution Number	S00001273
Solution Title	Front end belt driven accessories
Update Reason	Solution Modified
Date	09-Jan-2022
Fault Code / Symptom	Vibration
Solution Number	S00001273
Solution Title	Front end belt driven accessories
Update Reason	Solution Reordered
Date	09-Jan-2022
Fault Code / Symptom	Vibration
Solution Number	S00001273
Solution Title	Front end belt driven accessories
Update Reason	Solution Modified
Date	05-Dec-2021
Fault Code / Symptom	Exhaust Leak
Solution Number	S00009631
Solution Title	Leaks in the exhaust system
Update Reason	Solution Added
Date	05-Dec-2021
Fault Code / Symptom	Exhaust Noise
Solution Number	S00009631
Solution Title	Leaks in the exhaust system
Update Reason	Solution Added

Date	31-Oct-2021
Fault Code / Symptom	Air Compressor Continuous Operation/Frequent Cycling
Solution Number	S00009631
Solution Title	Leaks in the exhaust system
Update Reason	Solution Removed
Date	31-Oct-2021
Fault Code / Symptom	Air Compressor Pumping Lubricating Oil
Solution Number	S00009631
Solution Title	Leaks in the exhaust system
Update Reason	Solution Removed
Date	31-Oct-2021
Fault Code / Symptom	Air Compressor Will Not Pump Air
Solution Number	S00009631
Solution Title	Leaks in the exhaust system
Update Reason	Solution Removed
Date	03-Oct-2021
Fault Code / Symptom	Fuel in the Coolant
Solution Number	
Solution Title	
Update Reason	Solution Set Removed
Date	19-Sep-2021
Fault Code / Symptom	Air Compressor Continuous Operation/Frequent Cycling
Solution Number	S00009627
Solution Title	Leaks in the intake air system
Update Reason	Solution Added
Date	19-Sep-2021
Fault Code / Symptom	Air Compressor Continuous Operation/Frequent Cycling
Solution Number	S00009631
Solution Title	Leaks in the exhaust system
Update Reason	Solution Added

Date	19-Sep-2021
Fault Code / Symptom	Air Compressor Pumping Lubricating Oil
Solution Number	S00009627
Solution Title	Leaks in the intake air system
Update Reason	Solution Added
Date	19-Sep-2021
Fault Code / Symptom	Air Compressor Pumping Lubricating Oil
Solution Number	S00009631
Solution Title	Leaks in the exhaust system
Update Reason	Solution Added
Date	19-Sep-2021
Fault Code / Symptom	Air Compressor Will Not Pump Air
Solution Number	S00009627
Solution Title	Leaks in the intake air system
Update Reason	Solution Added
Date	19-Sep-2021
Fault Code / Symptom	Air Compressor Will Not Pump Air
Solution Number	S00009631
Solution Title	Leaks in the exhaust system
Update Reason	Solution Added
Date	19-Sep-2021
Fault Code / Symptom	Black Smoke
Solution Number	S00009627
Solution Title	Leaks in the intake air system
Update Reason	Solution Added
Date	19-Sep-2021
Fault Code / Symptom	Black Smoke
Solution Number	S00009631
Solution Title	Leaks in the exhaust system
Update Reason	Solution Added

Date	19-Sep-2021
Fault Code / Symptom	Engine Speed Surges
Solution Number	S00009627
Solution Title	Leaks in the intake air system
Update Reason	Solution Added
Date	19-Sep-2021
Fault Code / Symptom	Engine Speed Surges
Solution Number	S00009631
Solution Title	Leaks in the exhaust system
Update Reason	Solution Added
Date	19-Sep-2021
Fault Code / Symptom	Fuel Consumption Excessive
Solution Number	S00009627
Solution Title	Leaks in the intake air system
Update Reason	Solution Added
Date	19-Sep-2021
Fault Code / Symptom	Fuel Consumption Excessive
Solution Number	S00009631
Solution Title	Leaks in the exhaust system
Update Reason	Solution Added
Date	19-Sep-2021
Fault Code / Symptom	Low Power
Solution Number	S00009627
Solution Title	Leaks in the intake air system
Update Reason	Solution Added
Date	19-Sep-2021
Fault Code / Symptom	Low Power
Solution Number	S00009631
Solution Title	Leaks in the exhaust system
Update Reason	Solution Added

Date	19-Sep-2021
Fault Code / Symptom	Turbocharger Noise
Solution Number	S00009627
Solution Title	Leaks in the intake air system
Update Reason	Solution Added
Date	19-Sep-2021
Fault Code / Symptom	Turbocharger Noise
Solution Number	S00009631
Solution Title	Leaks in the exhaust system
Update Reason	Solution Added
Date	12-Sep-2021
Fault Code / Symptom	Real Time Clock - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000443
Solution Title	ECM calibration revision history check
Update Reason	Solution Added
Date	12-Sep-2021
Fault Code / Symptom	Battery 1 Voltage - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00000443
Solution Title	ECM calibration revision history check
Update Reason	Solution Added
Date	25-Aug-2021
Fault Code / Symptom	Crank No Start
Solution Number	S00001276
Solution Title	Crankshaft/camshaft sensor
Update Reason	Solution Reordered
Date	25-Aug-2021
Fault Code / Symptom	Crank No Start
Solution Number	S00001276
Solution Title	Crankshaft/camshaft sensor
Update Reason	Solution Modified

Date	25-Aug-2021
Fault Code / Symptom	Lubricating Oil Filter Plugging
Solution Number	S00001886
Solution Title	Incorrect lubricating oil filter
Update Reason	Solution Added
Date	25-Aug-2021
Fault Code / Symptom	Lubricating Oil Pressure Low
Solution Number	S00001886
Solution Title	Incorrect lubricating oil filter
Update Reason	Solution Reordered
Date	25-Aug-2021
Fault Code / Symptom	Lubricating Oil Pressure Low
Solution Number	S00001886
Solution Title	Incorrect lubricating oil filter
Update Reason	Solution Modified
Date	08-Aug-2021
Fault Code / Symptom	Intake Manifold 1 Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00000485
Solution Title	Radiator is externally obstructed
Update Reason	Solution Added
Date	08-Aug-2021
Fault Code / Symptom	Intake Manifold 1 Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00000785
Solution Title	Thermostat is malfunctioning
Update Reason	Solution Added

Date	08-Aug-2021
Fault Code / Symptom	Intake Manifold 1 Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00001359
Solution Title	Out-of-chassis opening temperature test
Update Reason	Solution Added
Date	25-Jul-2021
Fault Code / Symptom	Fuel in the Lubricating Oil
Solution Number	S00005873
Solution Title	High fuel drain line restriction
Update Reason	Solution Removed
Date	25-Jul-2021
Fault Code / Symptom	Fuel in the Lubricating Oil
Solution Number	S00005875
Solution Title	Fuel gear pump is leaking fuel into the oil
Update Reason	Solution Removed
Date	25-Jul-2021
Fault Code / Symptom	Lubricating Oil Level High
Solution Number	S00005873
Solution Title	High fuel drain line restriction
Update Reason	Solution Removed
Date	25-Jul-2021
Fault Code / Symptom	Lubricating Oil Level High
Solution Number	S00005875
Solution Title	Fuel gear pump is leaking fuel into the oil
Update Reason	Solution Removed
Date	12-Jul-2021
Fault Code / Symptom	Intake Manifold 1 Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00000785
Solution Title	Thermostat is malfunctioning
Update Reason	Solution Removed

Date	12-Jul-2021
Fault Code / Symptom	Intake Manifold 1 Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00001359
Solution Title	Out-of-chassis opening temperature test
Update Reason	Solution Removed
Date	05-Jul-2021
Fault Code / Symptom	Air Compressor Pumping Coolant
Solution Number	S00009574
Solution Title	Air compressor cylinder head gasket or cylinder head is malfunctioning (two cylinder)
Update Reason	Solution Added
Date	05-Jul-2021
Fault Code / Symptom	Coolant Overflow
Solution Number	S00009574
Solution Title	Air compressor cylinder head gasket or cylinder head is malfunctioning (two cylinder)
Update Reason	Solution Added
Date	05-Jul-2021
Fault Code / Symptom	Coolant in the Lubricating Oil
Solution Number	S00009574
Solution Title	Air compressor cylinder head gasket or cylinder head is malfunctioning (two cylinder)
Update Reason	Solution Added
Date	05-Jul-2021
Fault Code / Symptom	Crank No Start
Solution Number	S00001217
Solution Title	Cranking State malfunction
Update Reason	Solution Reordered
Date	05-Jul-2021
Fault Code / Symptom	Crank No Start
Solution Number	S00001217
Solution Title	Cranking State malfunction
Update Reason	Solution Modified

Date	05-Jul-2021
Fault Code / Symptom	Internal Coolant Leak
Solution Number	S00009574
Solution Title	Air compressor cylinder head gasket or cylinder head is malfunctioning (two cylinder)
Update Reason	Solution Added
Date	30-May-2021
Fault Code / Symptom	Accelerator Pedal or Lever Position 1 Sensor Circuit Frequency - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00000443
Solution Title	ECM calibration revision history check
Update Reason	Solution Added
Date	30-May-2021
Fault Code / Symptom	Accelerator Pedal or Lever Position Sensor 1 - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00000443
Solution Title	ECM calibration revision history check
Update Reason	Solution Added
Date	09-May-2021
Fault Code / Symptom	Air Compressor Noise
Solution Number	S00001268
Solution Title	Air compressor damaged or excessively worn
Update Reason	Solution Added
Date	09-May-2021
Fault Code / Symptom	Air Compressor Will Not Pump Air
Solution Number	S00001268
Solution Title	Air compressor damaged or excessively worn
Update Reason	Solution Added
Date	27-Apr-2021
Fault Code / Symptom	Blue Smoke
Solution Number	S00005141
Solution Title	Crankcase Blowby Check
Update Reason	Solution Reordered

Date	27-Apr-2021
Fault Code / Symptom	Blue Smoke
Solution Number	S00005141
Solution Title	Crankcase Blowby Check
Update Reason	Solution Modified
Date	27-Apr-2021
Fault Code / Symptom	High Blowby
Solution Number	S00005141
Solution Title	Crankcase Blowby Check
Update Reason	Solution Reordered
Date	27-Apr-2021
Fault Code / Symptom	High Blowby
Solution Number	S00005141
Solution Title	Crankcase Blowby Check
Update Reason	Solution Modified
Date	27-Apr-2021
Fault Code / Symptom	Lubricating Oil Filter Plugging
Solution Number	S00001322
Solution Title	Cracked fuel injector body or damaged injector o-ring
Update Reason	Solution Removed
Date	18-Apr-2021
Fault Code / Symptom	Cranks Slowly
Solution Number	S00001223
Solution Title	Solenoid on starter motor is malfunctioning
Update Reason	Solution Reordered
Date	18-Apr-2021
Fault Code / Symptom	Cranks Slowly
Solution Number	S00001223
Solution Title	Solenoid on starter motor is malfunctioning
Update Reason	Solution Modified

Date	18-Apr-2021
Fault Code / Symptom	Will Not Crank
Solution Number	S00001223
Solution Title	Solenoid on starter motor is malfunctioning
Update Reason	Solution Reordered
Date	18-Apr-2021
Fault Code / Symptom	Will Not Crank
Solution Number	S00001223
Solution Title	Solenoid on starter motor is malfunctioning
Update Reason	Solution Modified
Date	18-Apr-2021
Fault Code / Symptom	Ambient Air Temperature Sensor 1 Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000833
Solution Title	Ambient air temperature sensor open circuit check
Update Reason	Solution Removed
Date	11-Apr-2021
Fault Code / Symptom	Intake Manifold 1 Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00000311
Solution Title	Charge air cooler or exhaust system leak
Update Reason	Solution Removed
Date	28-Feb-2021
Fault Code / Symptom	Water in Fuel Indicator - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00000545
Solution Title	Water accumulation in the fuel filter
Update Reason	Solution Reordered

Date	28-Feb-2021
Fault Code / Symptom	Water in Fuel Indicator - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00000545
Solution Title	Water accumulation in the fuel filter
Update Reason	Solution Modified
Date	28-Feb-2021
Fault Code / Symptom	Water in Fuel Indicator - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	
Solution Title	
Update Reason	Solution Set Added
Date	17-Jan-2021
Fault Code / Symptom	Engine Shut Down Hot - Condition Exists
Solution Number	
Solution Title	
Update Reason	Solution Set Added
Date	17-Jan-2021
Fault Code / Symptom	Fuel in the Coolant
Solution Number	S00002937
Solution Title	Contaminated coolant supply
Update Reason	Solution Removed
Date	17-Jan-2021
Fault Code / Symptom	Fan Control Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00001060
Solution Title	Fan control solenoid circuit pin to ground short
Update Reason	Solution Reordered
Date	17-Jan-2021
Fault Code / Symptom	Fan Control Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00001060
Solution Title	Fan control solenoid circuit pin to ground short
Update Reason	Solution Modified

Date	17-Jan-2021
Fault Code / Symptom	Intake Manifold 1 Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00008386
Solution Title	Leaks in the intake air system
Update Reason	Solution Added

Date	17-Jan-2021
Fault Code / Symptom	Intake Manifold 1 Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00008815
Solution Title	Charge air cooler system leak
Update Reason	Solution Added

Date	17-Jan-2021
Fault Code / Symptom	Intake Manifold Pressure Sensor Circuit - Data erratic, intermittent or incorrect
Solution Number	S00000025
Solution Title	Restricted intake air filter
Update Reason	Solution Added

Date	17-Jan-2021
Fault Code / Symptom	Intake Manifold Pressure Sensor Circuit - Data erratic, intermittent or incorrect
Solution Number	S00008386
Solution Title	Leaks in the intake air system
Update Reason	Solution Added

Date	17-Jan-2021
Fault Code / Symptom	Intake Manifold Pressure Sensor Circuit - Data erratic, intermittent or incorrect
Solution Number	S00008815
Solution Title	Charge air cooler system leak
Update Reason	Solution Added

Date	10-Jan-2021
Fault Code / Symptom	Engine Control Module Critical Internal Failure - Bad Intelligent Device or Component
Solution Number	S00008831
Solution Title	ECM Malfunction
Update Reason	Solution Added
Date	10-Jan-2021
Fault Code / Symptom	Engine Control Module Critical Internal Failure - Bad Intelligent Device or Component
Solution Number	S00001622
Solution Title	ECM Malfunction
Update Reason	Solution Removed
Date	29-Nov-2020
Fault Code / Symptom	High Blowby
Solution Number	S00001256
Solution Title	Plugged external crankcase breather tube
Update Reason	Solution Removed
Date	08-Nov-2020
Fault Code / Symptom	Blue Smoke
Solution Number	S00001256
Solution Title	Plugged external crankcase breather tube
Update Reason	Solution Removed
Date	17-Oct-2020
Fault Code / Symptom	Injector Solenoid Driver 5 Circuit - Current Below Normal or Open Circuit
Solution Number	S00002437
Solution Title	Check for primary fault codes
Update Reason	Solution Removed
Date	17-Oct-2020
Fault Code / Symptom	Injector Solenoid Driver 3 Circuit - Current Below Normal or Open Circuit
Solution Number	S00002154
Solution Title	Check for primary fault codes
Update Reason	Solution Removed

Date	17-Oct-2020
Fault Code / Symptom	Injector Solenoid Driver 2 Circuit - Current Below Normal or Open Circuit
Solution Number	S00001832
Solution Title	Check for primary fault codes
Update Reason	Solution Removed
Date	17-Oct-2020
Fault Code / Symptom	Injector Solenoid Driver 2 Circuit - Current Below Normal or Open Circuit
Solution Number	S00007755
Solution Title	Check for primary fault codes
Update Reason	Solution Removed
Date	17-Oct-2020
Fault Code / Symptom	
Solution Number	
Solution Title	
Update Reason	QSM11 CM570 New manual released for use.

Last Modified: 23-Aug-2026
