

Fault Code: 611

Keyswitch Hot Shutdown

 Printable Version

Overview

Codes	Reason	Effect
Fault Code: 611 PID(P): SPN: FMI: Lamp: None SRT:	Engine shut down with the keyswitch before proper engine cooldown.	No action is taken by ECM. Load factor above the maximum shutdown threshold. Fault code will be logged.

©Cummins Inc

Circuit Description

nonapplicable for this fault code

Component Location

nonapplicable for this fault code

(/qs3/pubsys2/xml/en/procedures/--.html)

Last Modified: 01-Mar-2011
