

Fault Code: 777

Turbocharger Air Inlet Temperature - Engine Protection

 Printable Version

Overview

Codes	Reason	Effect
Fault Code: 777 PID(P): SPN: FMI: Lamp: Yellow SRT:	The turbocharger inlet air temperature has exceeded the standard ambient air temperature limit.	The engine will go into a derate mode until the turbocharger inlet air temperature drops to a normal level.

©Cummins Inc

Circuit Description

nonapplicable for this fault code

Component Location

nonapplicable for this fault code

Shoptalk

Inspect the air intake for blockage, proximity to any heating elements, or proximity to the exhaust system.

(/qs3/pubsys2/xml/en/procedures/--.html)

Last Modified: 01-Mar-2011
