

Trainings ▾

Remove

Using puller, Part Number ST-647, remove the pulley from the alternator drive pulley shaft.

Remove the puller.

