


Fault Code: 2155

Post-Oil Filter Pressure Sensor Circuit - Voltage Below Normal or Shorted to Low Source

 Printable Version

Overview

Codes	Reason	Effect
Fault Code: 2155 PID(P): 100 SPN: 611 FMI: 4 Lamp: None SRT: 00-686	Post-Oil Filter Pressure Sensor Circuit - Voltage Below Normal or Shorted to Low Source. Low voltage detected on SIGNAL pin 09 of the main harness A ECM connector.	Fault Code 612 is disabled.



Post-Filter Oil Pressure Sensor Circuit

Circuit Description

The post-filter oil pressure is the engine oil pressure after the oil has passed through the oil filters. The post-filter oil pressure sensor sends the post-filter oil pressure signal to the CENSE™ ECM.

Component Location

The post-filter oil pressure sensor is located on the oil outlet side of the lubricating oil system filter head.

Shoptalk

- If the fault occurs **only** in a cold environment, allow the oil to warm up and see if the fault becomes inactive.

Refer to Troubleshooting Fault Code t05-2155 (</qs3/pubsys2/xml/en/procedures/81/81-t05-2155.html>)

Last Modified: 07-Jul-2015
