


Fault Code: 612

Engine Oil Filter Differential Pressure - Data Valid But Below Normal Operating Range - Most Severe Level

 Printable Version

Overview

Codes	Reason	Effect
Fault Code: 612 PID(P): P99 SPN: 099 FMI: 1 Lamp: Red SRT: CE-612	Engine Oil Filter Differential Pressure - Data Valid But Below Normal Operating Range - Most Severe Level. The difference in pre-oil filter pressure and post-oil filter pressure indicates that the lubricating oil filter is restricted.	Possible reduced engine performance.



Pre-Oil Filter Pressure Sensor Circuit

Circuit Description

The pre-oil filter pressure is the engine oil pressure before the oil has passed through the oil filter. The pre-oil filter pressure sensor is located on the oil inlet side of the lubricating oil system.

The post-oil filter pressure is the engine oil pressure after the oil has passed through the oil filter.

Component Location

Use the following procedure for component location. Refer to Procedure 100-002 in Section E.
(/qs3/pubsys2/xml/en/procedures/81/81-100-002.html)

Refer to Troubleshooting Fault Code 612. (/qs3/pubsys2/xml/en/procedures/81/81-t05-612.html)

Last Modified: 28-Oct-2022
