



Technical Service Bulletin

Technical Service Bulletin: tsb100464	Released Date: 10-Aug-2007
Release of Flat Cooling Plate Pistons	

Release of Flat Cooling Plate Pistons

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Technical Service Bulletin is superseded by topic 07T1-44 (T2977). Please replace this topic with topic 07T1-44 (T2977).

Last Modified: 10-Aug-2007
