



Technical Service Bulletin

Technical Service Bulletin: tsb100672

Released Date: 21-Feb-2008

Water Pump Rebuild Kit

Water Pump Rebuild Kit

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Technical Service Bulletin introduces a new ISM/QSM water pump rebuild kit which obsoletes and supersedes the old water pump rebuild kit, as indicated in the table below. The new water pump rebuild kit contains a new water seal which provides increased resistance to the entrance of abrasive material.

It is necessary to use the correct water seal installation tool, Part Number 4918797, with this kit.

Water Pump Rebuild Kit Part Numbers

Description	Old Part Number	New Part Number
Kit, Water Pump Repair	4024817	4955802

Last Modified: 21-Feb-2008