



Technical Service Bulletin

Technical Service Bulletin: tsb100929

Released Date: 29-Apr-2010

New Water Outlet Connection

New Water Outlet Connection

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Technical Service Bulletin announces the introduction of a new water outlet connection, Part Number 5261014, manufactured from Polyamide HTN51, to replace the present, water outlet connection Part Number 3943300, manufactured from metal.




Figure1 - New Part Number 5261014 and Figure 2 - Old Part Number 3943300

The new design incorporates the addition of ribs and compression limiters to strengthen the part and distribute stress loads. There is no change to the location interface or fastening process.

Outside Diameter		Inside Diameter		Pipe Wall Thickness	
Old	New	Old	New	Old	New
44.45 mm	44.45 mm	41.15 mm	38.45 mm	1.15 mm	3.0 mm

Last Modified: 29-Apr-2010
