



Technical Service Bulletin

Technical Service Bulletin: tsb100930

Released Date: 12-Mar-2010

New Front Gear Cover Strip Seal

New Front Gear Cover Strip Seal

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Technical Service Bulletin supersedes topic 05T1-20. Please replace 05T1-20 with this topic.

This Technical Service Bulletin introduces a new front gear cover strip seal. This improvement has been made to address front gear cover oil leaks in the field.

The new strip seal is rust in color and has a dog bone cross-section as compared to the old black strip seal with an oval cross-section.

This Topic includes the following:

- New and old part numbers (Table 1)
- New and old kit numbers that contain the front gear cover strip seal (Table 2).

Table 1: New and Old Part Numbers

Description	New Part Number	Old Part Numbers
Seal, strip (front gear cover)	4920751	3893812, 3893964

Table 2: New and Old Kit Part Numbers				
Description	New Kit Part Number	Old Kit Part Number	Kit Description	
Kit, rectangular strip seal	4089995	4025151	• One rectangular strip seal (4920751) • 38 hex-flangeS head capscr ews (4070462) • Five hex-flange head capscr ews (4070463)	

Table 2: New and Old Kit Part Numbers				
Description	New Kit Part Number	Old Kit Part Number	Kit Description	
Kit, gear cover	4089996	4070537	• Gear cover (34008 11) • One rectangular strip seal (49207 51) • 33 hex-flange head cap screws (40704 62) • Five hex-flange head cap screws (40704 63) • One gear cover plug (40829 74)	

Table 2: New and Old Kit Part Numbers				
Description	New Kit Part Number	Old Kit Part Number	Kit Description	
Kit, gear cover	4089997	4070537	• Gear cover (38926 97) • One rectangular strip seal (49207 51) • 38 hex-flange head cap screws (40704 62) • One gear cover plug (40829 74)	
Lower engine gasket set	4089998	4089479	• Complete lower engine gasket set	