



Technical Service Bulletin

Technical Service Bulletin: TSB101044	Released Date: 17-Feb-2021
New Injector Camshaft Follower Assembly for K19, K38, and K50 Engines.	

New Injector Camshaft Follower Assembly for K19, K38, and K50 Engines.

Core Issue

The new injector camshaft follower assembly contains a camshaft follower lever, pin, socket, and a complex crown roller. The complex crown roller and camshaft follower lever have been released for continuous product improvement.

Part numbers have also been made common across K19, K38, and K50 engine platforms.

Confirmation

Excessive noise from the overhead and white smoke from the exhaust may be observed if camshaft follower or camshaft lobe damage has occurred.

Resolution

During engine repair or rebuild, new and old style camshaft follower assemblies should **not** be mixed. The Injector Camshaft Follower Assembly removal and installation procedure remains unchanged. It is **not** recommended to mix old and new camshaft follower levers, with old and new camshaft follower rollers. The (old) narrow camshaft follower roller continues to be available for service **only**.

Note : There is no change to the installation procedure.

Note : New and old camshaft follower assemblies should **not** be mixed within an engine.

The new camshaft follower assembly went into production at all engine plants during August, 2010. Daventry Engine Plant (K38/50 series engines) Engine Serial Number (ESN) first is 33182371. Cummins India Ltd (CIL) Engine Plant (K19/38/50 series engines) ESN first is to be determined. Seymour Engine Plant (K19 series engines) ESN first is to be determined.

	Old Part Numbers			New Part Number
Name	"Narrow" Roller	"Wide" Roller	"Complex Crown" Roller	"Complex Crown" Roller and New Camshaft Follower Lever
Camshaft Follower Assembly				
Lever, Cam Follower	AR10627	3078180	3635817	3642502
Injector Camshaft Follower Lever Assembly				
Lever, Cam Follower	AR10626	3081413	3635816	3642503
Injector Camshaft Follower Assembly Components				
Socket, Cam Follower	213559	213559	213559	213559
Lever, Cam Follower	206231	3081411	3081411	3642504
Roller, Cam Follower	3016825	3062141	3635815	3642505
Pin, Cam Follower Roller	4009479	4009479	4009479	4009479

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Document History

Date	Details
2010-8-30	Module Created
2014-1-20	none
2021-2-17	Made changes to wording found throughout procedure.

Last Modified: 17-Feb-2021
