



Technical Service Bulletin

Technical Service Bulletin: tsb101188	Released Date: 28-Aug-2002
Camshaft End Clearance Specification Change	

Camshaft End Clearance Specification Change

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This service/parts topic is being issued to update the camshaft end clearance specification. The current camshaft end clearance, 0.13 to 0.33 mm [0.005 to 0.013 in], changes to 0.13 to 0.41 mm [0.005 to 0.016 in]. An improved factory engine assembly process to install the camshaft gear allows this increased tolerance range.

Last Modified: 28-Aug-2002
