



Technical Service Bulletin

Technical Service Bulletin: tsb101624

Released Date: 30-Mar-2005

Oil Pan Mounting Capscrew Torque Change

Oil Pan Mounting Capscrew Torque Change

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic updates the oil pan mounting capscrew torque specification in Procedure 007-025 (Lubricating Oil Pan). This change updates the service torque specification to the value currently being used in the factory. The new torque specification is to be used for **all** field repairs.

New Torque Specification	Old Torque Specification
54 N•m [40 ft-lb]	47 N•m [35 ft-lb]

Note : This is a product improvement and not subject to campaign.

Related Procedures

101-007-025 (/qs3/pubsys2/xml/en/procedures/101/101-007-025.html)	Lubricating Oil Pan (/qs3/pubsys2/xml/en/procedures/101/101-007-025.html)
--	--

Last Modified: 30-Mar-2005