



Technical Service Bulletin

Technical Service Bulletin: tsb101698

Released Date: 21-Jul-2005

Change in Engine Brake Running Clearance Minimum Specifications

Change in Engine Brake Running Clearance Minimum Specifications

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts topic introduces a change in the minimum specification of the engine brake rocker lever running clearance for the Signature, ISX, and QSX15 engines. The change has been made to add a safety margin to accommodate exhaust valve stem growth.

The table below contains the new and the previous running clearance limits.

	mm		in
Previous Specification	0.508	MIN	0.020
	2.79	MAX	0.110
New Specification	0.635	MIN	0.025
	2.79	MAX	0.110

Related Procedures

10-003-004
(/qs3/pubsys2/xml/en/procedures/10/10-003-004.html)

Overhead Set
(/qs3/pubsys2/xml/en/procedures/10/10-003-004.html)

Last Modified: 21-Jul-2005

