



Technical Service Bulletin

Technical Service Bulletin: tsb101755

Released Date: 17-Jun-2009

Revision to Crankshaft Gear, Adapter, and Tone Wheel Procedure

Revision to Crankshaft Gear, Adapter, and Tone Wheel Procedure

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

Note : This Service/Parts Topic supersedes Topic 07T1-1; replace 07T1-1 with this topic.

Note : This is a product improvement and is not subject to campaign.

This Service/Parts Topic provides information for the removal and installation of the Crankshaft Adapter (Procedure 001-017), Crankshaft Gear (Procedure 001-018), and the Crankshaft Tone Wheel (Procedure 001-069). These procedures were developed to avoid the unnecessary replacement of the crankshaft in the field due to a crankshaft adapter, crankshaft gear or tone wheel repair.

Related Procedures

10-001-017-tr (/qs3/pubsys2/xml/en/procedures/10/10-001-017-tr.html)	Crankshaft Adapter (/qs3/pubsys2/xml/en/procedures/10/10-001-017-tr.html)
10-001-018 (/qs3/pubsys2/xml/en/procedures/10/10-001-018.html)	Crankshaft Gear, Front (Crankshaft Installed) (/qs3/pubsys2/xml/en/procedures/10/10-001-018.html)
10-001-069 (/qs3/pubsys2/xml/en/procedures/10/10-001-069.html)	Crankshaft Tone Wheel (/qs3/pubsys2/xml/en/procedures/10/10-001-069.html)

