



Technical Service Bulletin

Technical Service Bulletin: tsb101845

Released Date: 03-Mar-2006

Service Tool Page Revision

Service Tool Page Revision

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic provides information on the Cylinder Head Fuel Passage Leak Test Kit, Part Number 3164943, for the Signature, ISX, and QSX15 series engines.

Related Procedures

10-022-001
(/qs3/pubsys2/xml/en/procedures/10/10-022-001.html)

Service Tools
(/qs3/pubsys2/xml/en/procedures/10/10-022-001.html)

Last Modified: 03-Mar-2006