



# Technical Service Bulletin

Technical Service Bulletin: tsb102122

Released Date: 21-Feb-2007

Revision, Initial Check, (Air Leaks, Air Intake and Exhaust System) Procedure

## Revision, Initial Check, (Air Leaks, Air Intake and Exhaust System) Procedure

### Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

### Contents

This Service/Parts Topic is to update Procedure 010-024, Initial Check, (Air Leaks, Air Intake and Exhaust System). This update revises the Initial Check step to include disassembly and cleaning of the intake system as required.

### Related Procedures

10-010-024  
(/qs3/pubsys2/xml/en/procedures/10/10-010-024.html)

Air Leaks, Air Intake and Exhaust Systems  
(/qs3/pubsys2/xml/en/procedures/10/10-010-024.html)

Last Modified: 21-Feb-2007