



Technical Service Bulletin

Technical Service Bulletin: tsb102157

Released Date: 22-Feb-2007

Revision, Summary Data, Overhead Set Procedure

Revision, Summary Data, Overhead Set Procedure

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic revises the summary data of Procedure 003-004, Overhead Set, in the Signature, ISX, and QSX15 Service Manual, Bulletin 3666239. The correct maximum and minimum brake running clearance is now specified.

Related Procedures

10-003-004-tr
(/qs3/pubsys2/xml/en/procedures/10/10-003-004-tr.html)

Overhead Set
(/qs3/pubsys2/xml/en/procedures/10/10-003-004-tr.html)

Last Modified: 22-Feb-2007