



Technical Service Bulletin

Technical Service Bulletin: tsb102279

Released Date: 07-May-2007

Revision, Install Step, Piston and Connecting Rod Assembly Procedure

Revision, Install Step, Piston and Connecting Rod Assembly Procedure

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic adds the specification for connecting rod and crankshaft side clearance when reusing the same connecting rod and crankshaft on the same journal of the crankshaft.

Related Procedures

18-001-054-tr
(/qs3/pubsys2/xml/en/procedures/18/18-001-054-tr.html)

Piston and Connecting Rod Assembly
(/qs3/pubsys2/xml/en/procedures/18/18-001-054-tr.html)

Last Modified: 07-May-2007