



Technical Service Bulletin

Technical Service Bulletin: tsb102603

Released Date: 17-Dec-2007

Revision, Specifications Section, Cooling System Procedure

Revision, Specifications Section, Cooling System Procedure

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

The purpose of this Service/Parts topic is to revise Procedure 018-018 (Cooling System) in Section V of the Service Manual Signature, ISX, and QSX15, Bulletin 3666239. The specification for Maximum Coolant Pressure has been changed.

Related Procedures

10-018-018-tr
(/qs3/pubsys2/xml/en/procedures/10/10-018-018-tr.html)

Cooling System
(/qs3/pubsys2/xml/en/procedures/10/10-018-018-tr.html)

Last Modified: 17-Dec-2007