



Technical Service Bulletin

Technical Service Bulletin: tsb102856

Released Date: 12-May-2008

(Crankshaft Seal, Rear) Procedure, Remove and Install Section Revisions

(Crankshaft Seal, Rear) Procedure, Remove and Install Section Revisions

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic revises Procedure 001-024 (Crankshaft Seal, Rear) to add information regarding the use of the rear crankshaft seal replacer kit, Part Number 3164780, and spacer, Part Number 4918688.

Related Procedures

10-001-024-tr
(/qs3/pubsys2/xml/en/procedures/10/10-001-024-tr.html)

Crankshaft Seal, Rear
(/qs3/pubsys2/xml/en/procedures/10/10-001-024-tr.html)

Last Modified: 12-May-2008