



Technical Service Bulletin

Technical Service Bulletin: tsb102871

Released Date: 20-Jun-2008

Maintenance Schedule Addition

Maintenance Schedule Addition

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic introduces crankcase breather element replacement to Section 6 of Procedure 102-002 (Maintenance Schedule).

Related Procedures

10-102-002-om-ind
(/qs3/pubsys2/xml/en/procedures/10/10-102-002-om-ind.html)

Maintenance Schedule
(/qs3/pubsys2/xml/en/procedures/10/10-102-002-om-ind.html)

Last Modified: 20-Jun-2008