



Technical Service Bulletin

Technical Service Bulletin: tsb102922	Released Date: 10-Jul-2008
New Lubricating Oil Filter Plugged Symptom Tree	

New Lubricating Oil Filter Plugged Symptom Tree

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic introduces a Lubricating Oil Filter Plugged symptom tree to the Signature™, ISX, and QSX15 Service Manual, Bulletin 3666239.

Lubricating Oil Filter Plugged

Last Modified: 10-Jul-2008
