



Technical Service Bulletin

Technical Service Bulletin: tsb103100

Released Date: 09-Oct-2008

Service Tools Addition

Service Tools Addition

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic adds the injector protrusion gauge to the Cylinder Head Service Tools Procedure in the K19 Service Manual, Bulletin 4021499.

Related Procedures

18-022-001_02
(/qs3/pubsys2/xml/en/procedures/18/18-022-001_02.html)

Service Tools
(/qs3/pubsys2/xml/en/procedures/18/18-022-001_02.html)

Last Modified: 09-Oct-2008