



Technical Service Bulletin

Technical Service Bulletin: tsb103232

Released Date: 05-Dec-2008

(Crankshaft Seal, Rear) Procedure, Multiple Section Revisions

(Crankshaft Seal, Rear) Procedure, Multiple Section Revisions

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic revises Procedure 001-024 (Crankshaft Seal, Rear) in Section 1. Revisions include clarification on proper orientation and installation of the rear crankshaft seal and spacer used for installation. In addition, measurement specifications for protusion and squareness for the rear crankshaft seal have been added to make sure of the proper installation depth and orientation.

Related Procedures

10-001-024-tr
(/qs3/pubsys2/xml/en/procedures/10/10-001-024-tr.html)

Crankshaft Seal, Rear
(/qs3/pubsys2/xml/en/procedures/10/10-001-024-tr.html)

Last Modified: 05-Dec-2008