



Technical Service Bulletin

Technical Service Bulletin: tsb103672

Released Date: 21-Jan-2010

Maintenance Schedule Revision

Maintenance Schedule Revision

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic revises the Maintenance Schedule, removing the 'Crankshaft and clearance - Inspect/Measure' in Section 6.

Related Procedures

18-102-002
(/qs3/pubsys2/xml/en/procedures/18/18-102-002.html)

Maintenance Schedule
(/qs3/pubsys2/xml/en/procedures/18/18-102-002.html)

Last Modified: 21-Jan-2010